From:
To: Sean Simonsor

Subject: Proposed 2022 Northwest (NW) Area Mill and Overlay Project

Date: Monday, August 09, 2021 9:33:11 AM

CAUTION: This email originated from outside of the organization.

Dear Sean Simonson,

I am writing in regard to concerns that I have about the proposed off-street trail along the north side of North Avenue as well as concerns that I have about the tagged trees on Woodland Trail.

As for the off-street trail, I am primarily concerned with the number of mature trees that would be removed. It seems extreme to remove mature trees when there are available sidewalks and a bike path could simply be spray painted on. My family walks around this area on a daily basis and I rarely see other people out, so destroying trees to make a trail doesn't make sense to me. I deeply value trees and the benefits they bring to the community, especially during these difficult times humans are facing from climate change.

Because mature trees bring so much value to a community, I am worried about the tagged trees on Woodland Trail. From what I understand the city has used a company that is not local and does not understand the unique characteristics of this area that will not only rate the trees on a scale of 0-10, but will cut any trees down that rate three and under. It seems like a conflict of interest to have an out of town business that will also be paid per tree they cut down to assess the trees. Ideally, an arborist that specializes in keeping nature intact would assess the trees. It is the tree canopy that makes Woodland Trail unique, and cutting too many trees down may quickly ruin the benefit the canopy offers. At this time I would like to share that majority of my left ear was removed from melanoma skin cancer. One of the main reasons my husband and I purchased our home on second is because of the shade that the canopy provides to lessen the potential negative effects that sun may have regarding skin cancer. The tree canopy is not only a benefit to me, it is a benefit to the people that walk and run on this street as well as the birds and other critters that live in it and benefit everyone in the community.

I understand that the city is proposing to replace cut down trees at a 2:1 ratio. This isn't a viable option. The trees to be used in the 2:1 ratio are not mature and they may or may not make it. If too many mature trees are removed the landscape will be drastically altered and birds and other important creatures will lose their habitat. Furthermore, trees live in a complex system with multiple mother trees that have the capacity to heal other trees within the system. By removing the mature trees, the city will be removing mother trees, which will put the remaining trees in jeopardy. Removing mature trees comes at a great risk. Keeping mature trees in place continues to add value to our community and it costs significantly less than purchasing, planting, and maintaining trees that might not even make

it without mother trees.

I would also like to take a moment to be a voice for my two young daughters and all the children of our community. The physical effects of climate change have started and will continue to get worse if we don't act. More than ever, we need to work together to keep mature trees and nature intact for future generations. Please use your power to make choices that include protecting and creating natural spaces for all citizens, not just on Woodland Trail, but everywhere in the city.

Northfield is a great place to live and I appreciate the hard work that you do. Thanks for taking the time to read this message.

With deep concern for the trees,

From: To:

Sean Simonson

Subject: Online Form Submittal: Email Sean Simonson Date: Sunday, August 08, 2021 8:21:39 AM

CAUTION: This email originated from outside of the organization.

Email Sean Simonson

To: Sean Simonson

First Name

Last Name

Reply Email

Subject

Mill and Overlay Project 2022

File Upload

Mill and Overlay Letter--

Comments August 9, 2021

To: Sean Simonson, Rhonda Pownell, David Bennett, Bryan Hadley, Ben Martig, George Zuccolotto

From:

Northfield, Mn 55057

Re: Trees and the 2022 Northwest Mill and Overlay Project 2022

We write to express concerns about the Mill and Overlay project scheduled for calendar year 2022.

We attended the July 14 meeting at Greenvale Park Elementary School but time and personnel limits made it hard for all community members to discuss their concerns at length. So we are raising some of our concerns in this letter.

Our home at is affected by this project at two physical points at least: (1) the front of the house (southside of the house) abutting Rolvaag Court and (2) the back of the house (northside of the house) abutting Thye Parkway (on the southside of Thye Parkway).

We have a number of concerns about the project overall, but here we focus on what is for us an especially serious matter. The fate of the trees on Thye Parkway.

We noted just before the July 14 meeting that trees on Thye

Parkway had been marked, and we wondered what this meant. We were told at the meeting that decisions on tree removals were yet to be made.

In the case of our property (to the southside of Thye Parkway) we have five trees that we planted at our expense on the boulevard a number of years ago (at different times) in order from east to west: two disease resistant elms, a swamp oak, a maple, and another swamp oak. (There were no trees at all on the boulevard or in our backyard when the property was purchased). These trees are now, after many years of hard cultivation and expense on our part, at the peak of their maturity. They beautify the street and they beautify our property. We planted these boulevard trees in the spirit of communal contribution and environmental sustainability.

Not to put too fine a point on the matter, we are appalled at the idea that these trees might be removed in the 2022 Mill and Overlay project. Indeed, we are troubled by the idea that any trees at commensurate levels of health and maturity on Thye Parkway might be removed for the sake of constructing a bicycle lane. The parkway is just now after many years beginning to look like a cultivated neighborhood rather than a barren highway strip. While we understand in principle the idea of bicycle lanes, we just don't think the traffic patterns on the parkway at all warrant construction tailoring that would involve the removal of mature healthy trees given aesthetic and environmental considerations. Bikers can easily bike now.

We urge you not to remove healthy mature trees on Thye Parkway as part of the 2022 Northwest Mill and Overlay Project.

We have other concerns and questions about the project but wanted to single out what is for us an especially important matter.

Thank you for your consideration.

Northfield, MN 55057

Email not displaying correctly?

From: Company Sean Simonson

Subject: Online Form Submittal: Email Sean Simonson Date: Thursday, August 05, 2021 3:18:42 PM

CAUTION: This email originated from outside of the organization.

Email Sean Simonson

To: Sean Simonson

First Name

Last Name

Reply Email

Subject

2022 Woodland Trail and North Avenue Street Project

File Upload

Comments

Sean, this is a more concise letter of my thoughts now that I have

Northfield Council Members and Mayor Pownell,

I am emailing you today regarding the proposed street construction project on Woodland Trail and North Avenue for 2022. It's my understanding you will be discussing this in your August work session and voting in September. I live at and our property backs up to North Avenue. We have lived here for 22 years and are very familiar with the neighborhood.

more facts and know the options (I attached a PDF as well):

The initial proposal we received from the City showed a new bike trail on the north side of North Avenue with no other options. We learned at the information meeting on July 14 that other on-street options were being considered. I am opposed to an off-street bike path on the north side of North Avenue due to the loss of literally hundreds of trees and significant drainage issues. These are physical issues, but there are also the immense costs involved in removing the trees and creating a drainage system. I am in favor of on-street bike lanes.

In an era when we are concerned about climate change and the need to plant trees, an off-street trail project would mandate the removal of hundreds of mature trees. In questioning a city engineer at the meeting, he thought it might be 1000 or more trees. Replacing a 12" diameter tree with two one-inch saplings will not replace the shade and CO2-reducing value of the 12" tree for approximately 30 years, if not longer. Also note 2000 new

trees need to be watered for a minimum of 18 months depending on size and drought conditions. Please drive along North Avenue to fully comprehend how many trees would have to be removed and replaced – and think of the associated cost.

Drainage has been a problem for decades in "Wang's Woods" and the George Rysgaard Preserve, the wooded area encompassing the Woodland Trail area neighborhood. Most water runoff runs south and collects in the woods on the north side of North Avenue with significant ponding. As heavy multipleinch rainfall events have become more common, this problem has worsened, resulting in significant standing water for days or weeks. I know some neighbors have had growing problems with seepage in their basements due to water leaching through the saturated soil. To give you an idea of the water issue, I have numerous neighbors who have sump pumps fail and have seen water in their basement within 12 hours. Installation of a paved bike trail and removal of trees would undoubtedly make the problem much worse. Rerouting of sump pump hoses might lessen the issue, but much of the problem is due to natural rainfall. To protect nearby homes and the new bike trail, fixing the drainage would be mandatory - and costly.

At the July 14th meeting, two on-street bike lane options were presented in addition to the off-street trail. My overriding question is what data has been used to predict the trail usage and traffic east of Cannon Valley Drive? I question the usage of a trail and making significant infrastructure changes without that data, so an option with a physical barrier makes the least sense at this point. I am 100% in favor of painted lanes on either side of the street. As a bicyclist myself, I find going against traffic disconcerting and I don't feel safe. As for physical barriers, I think they would be a real problem in the winter. They would be difficult for plows and cars to see and the snow would be dumped into the bike lane. That would force winter bikers and many runners into the vehicle right-of-way until the snow and ice melted. As for the off-street option, again as a bicyclist, I don't think I'd ever use an off-street bike path due to the necessity of stopping at every street crossing. For the growing number of electric-assisted bikes, this would be a problem as well. There is a sidewalk on the other side of the street to satisfy the Safe Routes to School initiative.

As for the mill/overlay project on Woodland Trail, the engineers say they have a right to remove anything on 12 feet on either side of Woodland Trail. They have tagged every tree in that buffer to document the trees. We were told they will only be trimming trees that interfere with the right-of-way and that they will not "clear cut" 12 feet on either side of the road. Some trimming is certainly in order. I welcome that, and I will take them at their word they will not clear cut 12 feet on either side of the roadway. I would also ask that any healthy tree deemed too

close to the road be moved instead of being cut down.

Email not displaying correctly?



ROADWAY PAVEMENT CONDITION

1.

PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

a.	Do you feel the pavement Please circle one:	surface has deterio	orated to the point it r NO	needs to be f	fixed?	
	FORM SEWER, STORM WA			SION		
	WE COURT, JUST			WITH	LUPINE	DRIVE
I have	e observed areas of erosion	along the boulevar	d at:			
Charles Services	nome or business have a su	mp pump? (addres	s).
	or <u>X</u> No				The second second	
Sec. 2 hand	d you be interested in a sum or No	p line extended be	yond the curb to hool	your sump	pump discha	arge to?
3. SA	NITARY SEWER					
	ave not experienced any pro ave experienced problems v).
4. W.	ATERMAIN					
	ave not experienced any pro ave experienced problems v),

Yes	e sidewalks or trails that you believe are missing that need to be added to the project
	s or X No
Yes, pl	lease provide location
33.3.4	
D 7	ffer any additional information you would like to be considered as a part of these improvements: THE LANDSCAPING IN THE LUPINE COURT CUL-DE-SAC 'CIRCLE'
D 7	THE LANDSCAPING IN THE LUPINE COURT CUL-DE-SAC 'CIRCLE' WAS IN BAD SHAPE FOR MANY YEARS.
D 7	THE LANDSCAPING IN THE LUPINE COURT CUL-DE-SAC 'CIRCLE' WAS IN BAD SHAPE FOR MANY YEARS. IN 2010 A GROUP OF US REMOVED MOST OF THE EXISTING OVERGROUND PHANTINGS, WEEDS AND ROCK. WE REPLACED THOSE
D 7	THE LANDSCAPING IN THE LUPINE COURT CUL-DE-SAC 'CIRCLE' WAS IN BAD SHAPE FOR MANY YEARS. IN 2020 A GROUP OF US REMOVED MOST OF THE EXISTING
D 7	THE LANDSCAPING IN THE LUPINE COURT CUL-DE-SAC 'CIRCLE' WAS IN BAD SHAPE FOR MANY YEARS. IN 2010 A GROUP OF US REMOVED MOST OF THE EXISTING OVERGROUND PLANTINGS, WEEDS AND ROCK. WE REPLACED THOSE WITH FRESH BLACK DIRT AND SOD. THE EXISTING GINKO TREE AND LILLIES WERE KEPT. WE
D 7	THE LANDSCAPING IN THE LUPINE COURT CUL-DE-SAC 'CIRCLE' WAS IN BAD SHAPE FOR MANY YEARS. IN 2010 A GROUP OF US REMOVED MOST OF THE EXISTING OVERCROWN PHANTINGS, WEEDS AND ROCK. WE REPLACED THOSE WITH FRESH BLACK DIRT AND SOD. THE EXISTING GINKO TREE AND LILLIES WE'RE KEPT. WE ALSO ADDED EDGING AND MULCH. PLEASE DO NOT MAKE ANY CHANCES TO THIS NEW LANDSCAPING
D 7	THE LANDSCAPING IN THE LUPINE COURT CUL-DE-SAC 'CIRCLE' WAS IN BAD SHAFE FOR MANY YEARS. IN 2010 A GROUP OF US REMOVED MOST OF THE EXISTING DYGROLDWN PHANTINGS, WEEDS AND ROCK. WE REPLACED THOSE WITH FRESH BLACK DIRT AND SOD. THE EXISTING GINKO TREE AND LILLIES WERE KEPT. WE ALSO ADDED EDGING AND MULCH. PLEASE DO NOT MAKE ANY CHANCES TO THIS NEW LANDSCAPING AS PART OF THIS MILL AND OVERLAY PROJECT IN 2022.
D 7	THE LANDSCHING IN THE LUPINE COURT CUL-DE-SAC 'CIRCLE' WAS IN BAD SHAPE FOR MANY YEARS. IN 2010 A GROUP OF US REMOVED MOST OF THE EXISTING OVERCODEN PHANTINGS, WEEDS AND ROCK. WE REPLACED THOSE WITH FRESH BLACK DIRT AND SOD. THE EXISTING GINKO TREE AND LILLIES WERE KEPT. WE ALSO ADDED EDGING AND MULCH. PLEASE DO NOT MAKE ANY CHANCES TO THIS NEW LANDSCAPING AS PART OF THIS MILL AND OVERLAY PROJECT IN 2022.

THANKS.

COMMENIS&FEE	DBACK
*NAME_	76 Sept. 188
*EMAIL	
*ADDRESS	
(* INDICATES OPTIONAL)	-
Circle your preffered bike facility concept:	
Thye Parkway (Map E): One-Way Separated Bike Lan	les Buffered Bike Lanes
North Avenue (Map F): Trail Two-way separated bike	
St. Olaf Avenue (Map G): Bike lanes Shared lanes	
- [10] [10] [10] [10] [10] [10] [10] [10]	Re Plan even concerted.
There was Absolutely No input from A	Desired to 1000 1 1 1000 1
It was All designed behind clos	sol doses the contract
You have offered only what the Mayor/ci	to the last strate last in the
WAWPolo How Tenni Ge of The North for Please leave your feedback in the comment box tonight or mail in with this directed to David Bennett at david.bennett@ci.northfield.mn.us or by phoshared with project staff and included in the project record. For more informn.us/1445/2022-NW-Area-Mill-and-Overlay-Project	is pre-addressed card. Comments may also be
2022 NW Area Mill &	Overlay
COMMENTS & FEET	DBACK
*NAME_	
*EMAIL_	
ADDRES	
* INDICATES OPTIONAL)	
Circle your preffered bike facility concept:	
Thye Parkway (Map E): One-Way Separated Bike Lane	
	ane (cycle track) Buffered bike lanes
St. Olaf Avenue (Map G): Bike lanes Shared lanes COMMENTS:	or just pais
Removing all the trees to do	a salden used to
bike that is expensive & ridicu	long A onth with
	onot a sood idea
Draine along North Ale in The	wals reals to 1. De
Please leave your feedback in the comment box tonight or mail in with this lirected to David Bennett at david bennett@ci.northfield.mn.us or by phor	pre-addressed card Comments may also be
hared with project staff and included in the project record. For more inform	mation on the project, go to https://ci.northfield.

	MENTS & FEEDBACK
*NAME_	
*EMAIL_	
*ADDRE	
(* INDICATES OPTIONAL)	
Circle your preffered bike facility concept: Thye Parkway (Map E): One-Way	Concreted Dilestance D. W. J. Dilest
	Separated Bike Lanes Buffered Bike Lanes
St. Olaf Avenue (Map G): Bike lai	-way separated bike lane (cycle track) Buffered bike lanes nes Shared lanes
COMMENTS: No bute +	rail on North.
Do L	
Paint is en	nough!
mn.us/1445/2022-NW-Area-Mill-and-Overlay-F	IW Area Mill & Overlay
CONTRACTOR OF THE STATE OF THE	MENTS & FEEDBACK
*NAME _	*PHONE
*EMAIL	, mone
*ADDRESS	
(* INDICATES OPTIONAL)	
Circle your preffered bike facility concept:	
Thye Parkway (Map E): One-Way	Separated Bike Lanes Buffered Bike Lanes Work
	way separated bike lane (cycle track) Buffered bike lanes
St. Olaf Avenue (Map G): Bike lar	nes Shared lanes
COMMENTS: Poor glan	
V	

Please leave your feedback in the comment box tonight or mail in with this pre-addressed card. Comments may also be directed to David Bennett at david.bennett@ci.northfield.mn.us or by phone at (507) 645-3006. Your feedback will be shared with project staff and included in the project record. For more information on the project, go to https://ci.northfield.mn.us/1445/2022-NW-Area-Mill-and-Overlay-Project

COMMENTS & FEEDBACK
*NAME
*EMAIL
*ADDRESS_
(* INDICATES OPTIONAL)
Circle your preffered bike facility concept:
Thye Parkway (Map E): One-Way Separated Bike Lanes (Buffered Bike Lanes)
North Avenue (Map F): Trail Two-way separated bike lane (cycle track) (Buffered bike lanes
St. Olaf Avenue (Map G): Bike lanes (Shared lanes)
COMMENTS: Thanks For taking the time to explain
the project and take comments
Please leave your feedback in the comment box tonight or mail in with this pre-addressed card. Comments may also be directed to David Bennett at david.bennett@ci.northfield.mn.us or by phone at (507) 645-3006. Your feedback will be shared with project staff and included in the project record. For more information on the project, go to https://ci.northfield.mn.us/1445/2022-NW-Area-Mill-and-Overlay-Project
2022 NW Area Mill & Overlay
COMMENTS & FEEDBACK
*NAME 5
*EMAIL_
*ADDRÉS
(* INDICATES OPTIONAL)
Circle your preffered bike facility concept:
Thye Parkway (Map E): One-Way Separated Bike Lanes Buffered Bike Lanes
North Avenue (Map F): Trail Two-way separated bike lane (cycle track) Buffered bike lanes
St. Olaf Avenue (Map G): Bike lanes Shared lanes
COMMENTS: Nice job handling the feistier elements of the meeting.
the Rysgaard Nature preserve. We've lost mature oaks to
high water.
Please leave your feedback in the comment box tonight or mail in with this pre-addressed card. Comments may also be

directed to David Bennett at david.bennett@ci.northfield.mn.us or by phone at (507) 645-3006. Your feedback will be shared with project staff and included in the project record. For more information on the project, go to https://ci.northfield.mn.us/1445/2022-NW-Area-Mill-and-Overlay-Project

COMMENTS & FEEDBACK
*NAME_ *EMAIL_ *ADDRES
(* INDICATES OPTIONAL)
Circle your preffered bike facility concept:
Thye Parkway (Map E): One-Way Separated Bike Lanes Buffered Bike Lanes North Avenue (Map F): Trail Two-way separated bike lane (cycle track) Buffered bike lanes St. Olaf Avenue (Map G): Bike lanes Shared lanes COMMENTS: PLEASE don't Lut any trees on Woodang Trail Two-way separated bike lane (cycle track) Buffered bike lanes COMMENTS: PLEASE don't Lut any trees on Woodang Moved there for Shade. People walk in the Comment of the Shade of the Sale bids of the Sale bids of the Sale bids of the Sale bids of the Comment box tonight or mail in with this pre-addressed card. Comments may also be directed to David Bennett at david.bennett@ci.northfield.mn.us or by phone at (507) 645-3006. Your feedback will be shared with project staff and included in the project record. For more information on the project, go to https://ci.northfield.mn.us/1445/2022-NW-Area-Mill-and-Overlay-Project
2022 NW Area Mill & Overlay
COMMENTS & FEEDBACK
*NAME; *EMAIL *ADDRE
(* INDICATES OPTIONAL)
Circle your preffered bike facility concept:
Thye Parkway (Map E): One-Way Separated Bike Lanes Buffered Bike Lanes
North Avenue (Map F): Trail Two-way separated bike lane (cycle track) Buffered bike lanes
St. Olaf Avenue (Map G): Bike lanes Shared lanes - Leave the Way 17/5.
DWellings, Arready hard to drive avoiding Parked costs with untiple a narrower street.
it. olatis also heavily used for Senitraffic.

Please leave your feedback in the comment box tonight or mail in with this pre-addressed card. Comments may also be directed to David Bennett at david.bennett@ci.northfield.mn.us or by phone at (507) 645-3006. Your feedback will be shared with project staff and included in the project record. For more information on the project, go to https://ci.northfield.mn.us/1445/2022-NW-Area-Mill-and-Overlay-Project

COMMENTS COMMENTS	& FEEDBACK
*NAME *EMAIL _£ *ADDRESS	
(* INDICATES OPTIONAL)	
Circle your preffered bike facility concept:	J Dila Laura Duffana J Dila Laura
Thye Parkway (Map E): One-Way Separated	
St. Olaf Avenue (Map G): Bike lanes Sha	rated bike lane (cycle track) Buffered bike lanes
the state of the s	
COMMENTS: PARTING 15 NECESS	ARY ON SP. OCAT AVE TO ACCOMIDATE PLE HOUSING, SEVERTE HOMES
HAVE ONLY ONE CAR GARGE.	
mn.us/1445/2022-NW-Area-Mill-and-Overlay-Project	For more information on the project, go to https://ci.northfield.
COMMENTS	&FEEDBACK
*NAME_	*PHONE
*EMAIL_	
*ADDRES	9
* INDICATES OPTIONAL)	
Circle your preffered bike facility concept:	
Thye Parkway (Map E): One-Way Separated	
North Avenue (Map F): Trail Two-way separa	ated bike lane (cycle track) Buffered bike lanes
	red lanes
COMMENTS: I'M POT IN FAVOR	OF THE TRAIL ON NORTH
AUCUUL. ATAM. I BIKE	North ASPRE-It is
- EIX	E- Very soft
	/ 0 0

Please leave your feedback in the comment box tonight or mail in with this pre-addressed card. Comments may also be directed to David Bennett at david.bennett@ci.northfield.mn.us or by phone at (507) 645-3006. Your feedback will be shared with project staff and included in the project record. For more information on the project, go to https://ci.northfield.mn.us/1445/2022-NW-Area-Mill-and-Overlay-Project

COI	MMENTS & FEEDBACK
*NAME	*PHONE I
*EMAIL	THORE TO SERVICE TO SE
*ADDRESS	
(* INDICATES OPTIONAL)	
Circle your preffered bike facility conce	pt:
Thye Parkway (Map E): One-W	Vay Separated Bike Lanes Buffered Bike Lanes
North Avenue (Map F): Trail T	wo-way separated bike lane (cycle track) Buffered bike lanes
St. Olaf Avenue (Map G): Bike	lanes Shared lanes
COMMENTS: Highland A	ve Sidewalks comes into the
middle of my fard be	efore crossing. Please put a
small angle to the	crossing to meet the sidewalk
between properties,	
Disease is	
directed to David Bennett at david.bennett	t box tonight or mail in with this pre-addressed card. Comments may also be @ci.northfield.mn.us or by phone at (507) 645-3006. Your feedback will be e project record. For more information on the project, go to https://ci.northfield.lay-Project
2022	2 NW Area Mill & Overlay
Company of the compan	MMENTS & FEEDBACK
*NAME	
*EMAIL	
*ADDRESS	
(* INDICATES OPTIONAL)	
Circle your preffered bike facility concep	t:
	ay Separated Bike Lanes Buffered Bike Lanes
North Avenue (Man F). Trail To	10-Way canagated bile lead of the lead of
St. Olar Avenue (Map G): Bike	lanes Shared lanes if this is a land
COMMENTS: I commute to	St. Olaf by bike from door-four. The best biles route
to BULLIN AVE IS 200 ST	e MN3 to Linden to 1st street west. Use the
nultiuse trail three Way Parle !	Much less that and useful to bile of 01

generations because the gradual (elevation change) is so much less Please leave your feedback in the comment box tonight or mail in with this pre-addressed card. Comments may also be directed to David Bennett at david.bennett@ci.northfield.mn.us or by phone at (507) 645-3006. Your feedback will be shared with project staff and included in the project record. For more information on the project, go to https://ci.northfield. mn.us/1445/2022-NW-Area-Mill-and-Overlay-Project

COMMENTS & FEEDBACK

*NAME *PHONE	
*EMAIL	
*ADDRESS	
(* INDICATES OPTIONAL)	
Circle your preffered bike facility concept:	
Thye Parkway (Map E): One-Way Separated Bike Lanes Buffered Bik	e Lanes
North Avenue (Map F): Trail Two-way separated bike lane (cycle track)	Buffered bike lanes
St. Olaf Avenue (Map G): Bike lanes Shared lanes	
COMMENTS: Having attended the JL 14TH mtg, and having listened well, la of Park & Rec do not meet with a great deal of approval by homeowner	
Ave. e.g. I trees replacing every one removed?? Scrawny trunks replacing 30	,40 year oil trees? No
Bike trail within a few feet of our homes? No. Noise & trash replacing per And for the chap who informed a questioner— Wang Wood is EAST of GVS—Not in Noteth Ave can certainly use mill of overlay— Hosvy fractic of large truess. Please leave your feedback in the comment box tonight or mail in with this pre-addressed card. O directed to David Bennett at david bennett@ci.northfield.mn.us or by phone at (507) 645-3006. shared with project staff and included in the project record. For more information on the project, mn.us/1445/2022-NW-Area-Mill-and-Overlay-Project	Noers — Comments may also be Your feedback will be

COMMENT	S & FFFDBACK
*NAME	*PHONE
*EMAIL *ADDRESS	The state of the s
(* INDICATES OPTIONAL)	0
Circle your preffered bike facility concept:	
Thye Parkway (Map E): One-Way Separate	ed Bike Lanes Buffered Bike Lanes
North Avenue (Map F): Trail Two-way sepa	arated bike lane (cycle track) (Buffered bike lanes
	nared lanes
COMMENTS: Stop the St. Olah	bike lane at Spring St. 40
elucourage bricyclists to los	uss #3 at 2nd Street by limbs
Spring Street to get to	W, 2nd St.
. 0	

Please leave your feedback in the comment box tonight or mail in with this pre-addressed card. Comments may also be directed to David Bennett at david.bennett@ci.northfield.mn.us or by phone at (507) 645-3006. Your feedback will be shared with project staff and included in the project record. For more information on the project, go to https://ci.northfield.mn.us/1445/2022-NW-Area-Mill-and-Overlay-Project



ROADWAY PAVEMENT CONDITION

1.

PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

	 Do you feel the pavement surface has deteriorated to the point it needs to be fixed? Please circle one: YES NO
2.	STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION
-	I have observed street ponding after a significant rain. It is located at:
_	I have observed areas of erosion along the boulevard at:
Doe	es your home or business have a sump pump? (address),
_	_Yes or No
If ye	es, would you be interested in a sump line extended beyond the curb to hook your sump pump discharge to?
_	Yes orNo
3.	SANITARY SEWER
=	We have not experienced any problems with our sanitary sewer serviceWe have experienced problems with our sanitary sewer service (address).
4.	WATERMAIN
	We have not experienced any problems with our water serviceWe have experienced problems with our water service (address).

5.	SIDEWALKS AND TRAILS (WALKING AND BIKING)
Are the	e sidewalks or trails that you believe are missing that need to be added to the project
	or No
	ease provide location
Add	a bicycle trail from 5th Street to Stolaf Ave near Cannon River.
-	
_	
6.	GENERAL COMMENTS / QUESTIONS
	GENERAL COMMENTS / QUESTIONS fer any additional information you would like to be considered as a part of these improvements:



2022 NW Area Mill and Overlay Project Northfield, Minnesota

1,	ROADWAY PAVEMENT CONDITION a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed? Please circle one: NO
2.	STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION
	I have observed street ponding after a significant rain. It is located at:
_	I have observed areas of erosion along the boulevard at:
Doe	s your home or business have a sump pump? (address
If ye	s, would you be interested in a sump line extended beyond the curb to hook your sump pump discharge to?
X	Yes or No Non-answer - no sump
3.	SANITARY SEWER
_	We have not experienced any problems with our sanitary sewer service. We have experienced problems with our sanitary sewer service (address).
4.	WATERMAIN
7	We have not experienced any problems with our water service. We have experienced problems with our water service (address).

	AND TRAILS (WALKING AND BIKING)
Are there sidewalks or	trails that you haliave are missing that need to be added to the project
11	trails that you believe are missing that need to be added to the project
Yes or No	
If Yes, please provide	ocation
Sidewalks m	issing between Sh. olah Ave and Summit Ave. on t. N., west side mostly but also both sides of points.
Proposed C	t. At a wirest side mostly but also hat like at points
- Or Courton	(1.) Me sur mostig out dies soft store of points.
-	
Please offer any addition	onal information you would like to be considered as a part of these improvements:



DONDWAY DAVEMENT CONDITION

PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

1,	a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed? Please circle one: NO
2.	STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION
-	have observed street ponding after a significant rain. It is located at:
	I have observed areas of erosion along the boulevard at:
	s your home or business have a sump pump? (address). Yes or No
If ye	es, would you be interested in a sump line extended beyond the curb to hook your sump pump discharge to? Yes or No
3.	SANITARY SEWER
X	We have not experienced any problems with our sanitary sewer serviceWe have experienced problems with our sanitary sewer service (address),
4.	WATERMAIN
X	

5. SIDEWALKS AND TRAILS (WALKING AND BIKING)	
Are there sidewalks or trails that you believe are missing that need to be added to the project	
Yes or No	
Spring Street has a lot of traffice of pledistrians. It would be safer if the entire length of Street between SHOlaf and Greenvale had sedewalk though That appears to be impossible.	
6. GENERAL COMMENTS / QUESTIONS Please offer any additional information you would like to be considered as a part of these improvements: Mu hanement believe at the Arminies School	
and St Olof (h) is in terrible shape. Churchs of the come! Loose livery winter causing the Dools and a nery trough, road. The of three years ago you inexplicated in street hostin of It Rominie School but not the lest of it.	×



2022 NW Area Mill and Overlay Project Northfield, Minnesota

The City values input from residents who live along the project corridor as you have first-hand knowledge of how the streets and utilities function. Your comments / concerns will assist us during the preliminary design and layout of the project. We encourage you to take a few minutes to fill out the following questionnaire. Completed questionnaires can be collected at the Neighborhood Meeting, emailed to Sean.Simonson@ci.northfield.mn.us or dropped off at the Engineering Office located at Northfield City Hall, 801 Washington Street.

	DOADIMAN DAVENERIT	COLIDITION
7	ROADWAY PAVEMENT	(,()VII)I I I I ()VI

a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed?

Please circle one: YESV NO

2. STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION	
I have observed street ponding after a significant rain. It is located at:	
I have observed areas of erosion along the boulevard at:	1000
Does your home or business have a sump pump? (address).
Yes orX_No	
f yes, would you be interested in a sump line extended beyond the curb to hook you	r sump pump discharge to?
Yes or No	
SANITARY SEWER	11
We have not experienced any problems with our sanitary sewer service. We have experienced problems with our sanitary sewer service (address).
WATERMAIN	
We have not experienced any problems with our water service.	


CIDENAL	AND TO AN A SHARE					
SIDEWALK	S AND TRAILS (WALK	ING AND BIKING)				
there sidewalks	or trails that you believe	are missing that nee	d to be added to the	project		
Yes or	lo .					
es, please provid	location	0	. A.	0		
Frease	see the	- to llow	ug lag			_
		77.5				
						1
1	BLATE OF		VAT -	ALA		
			7 7			-
OENED II		0110				
	COMMENTS / QUESTION (COMMENTS / QUESTION)		ered as a part of the	ese improvements	s:	
			lered as a part of the	ese improvements	S:	
			ered as a part of the	ese improvements	S:	
			lered as a part of th	ese improvement	S:	
			ered as a part of the	ese improvements	S:	
			ered as a part of the	ese improvements	S:	
			ered as a part of the	ese improvement	S:	
			ered as a part of the	ese improvements	S:	
			ered as a part of the	ese improvements	S:	
			ered as a part of the	ese improvement	S:	
			ered as a part of the	ese improvements	S:	
			lered as a part of the	ese improvements	S:	
			ered as a part of the	ese improvements	S:	
			ered as a part of the	ese improvements	S:	
			lered as a part of the	ese improvements	S:	


I would like the following points to be considered:

- 1) I am hoping that the railroad crossing on Saint Olaf Avenue will be improved to allow for the implementation of a silent crossing in the future. A railroad quiet zone would greatly benefit the community businesses, homes, church and school near the railroad crossing. I know that significant liability issues are involved with railroad crossings, but quiet zones can be implemented if the necessary improvements are made.
- 2) I am also hoping that some consideration will be given to address the steadily increasing traffic level on North Spring Street. As areas on the northwest part of town continue to be developed, more and more people are using North Spring Street as a passageway, rather than going out to the highway. This has created a very dangerous situation because North Spring Street is so narrow where it intersects Saint Olaf Avenue. There is no room for bicycle or pedestrian traffic for almost a city block along North Spring Street. The situation is particularly dangerous because of the speed that people drive as they turn the corner from Saint Olaf Avenue and head up North Spring Street. During the winter months, when the streets are slippery, there have been numerous times that vehicles have failed to make the corner cleanly and end up in my front yard.

I think that consideration should be given to the idea of making North Spring Street a one way street, allowing traffic to flow from north to south only. This would allow adequate space for a combined bike and pedestrian lane. There are wider streets to the west that could absorb the traffic flow from south to north, or people could drive out to MN highway 3.

I strongly feel that it is only a matter of time before a serious accident happens in this area if changes are not implemented. My primary concern is for the safety of the people who use North Spring Street.





2022 NW Area Mill and Overlay Project Northfield, Minnesota

The City values input from residents who live along the project corridor as you have first-hand knowledge of how the streets and utilities function. Your comments / concerns will assist us during the preliminary design and layout of the project. We encourage you to take a function. Your comments / concerns will assist us during the preliminary design and layout of the project. We encourage you to take a few minutes to fill out the following questionnaire. Completed questionnaires can be collected at the Neighborhood Meeting, emailed to Sean.Simonson@ci.northfield.mn.us or dropped off at the Engineering Office located at Northfield City Hall, 801 Washington Street.

ROADWAY PAVEMENT CONDITION a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed? Please circle one: YES NO NO NO NO NO NO NO NO NO N
2. STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION
X I have observed street ponding after a significant rain. It is located at:
Corner of Spring st. 2 greenvale Especially If storm drain
Does your home or business have a sump pump? (address).
XYes or No
If yes, would you be interested in a sump line extended beyond the curb to hook your sump pump discharge to?
_res or _ no be pending on inapact Impact & cost of installation
sanitary sewer and maintanence / on going use fees, if any
We have not experienced any problems with our sanitary sewer service. We have experienced problems with our sanitary sewer service (address
WATERMAIN 'Mto basement.
We have not experienced any problems with our water serviceWe have experienced problems with our water service (address).

	sidewalks or trails that you believe are missing that need to be added to the project
	or X No ase provide location
	ERAL COMMENTS / QUESTIONS ERAL COMMENTS / QUESTIONS The second discount of these improvements:
lease offer ar	by additional information you would like to be considered as a part of these improvements:
SCOPILALI	rest will polentially decrease the width of the
119 110	adventore availability of on street parking.
VI Gid	ewalk would not provide enough benefit to
The state	the negative impacts of narrowing the road.
do no	Ewanta side WAIK IF OUR NATION STreet WILL
e ino	acted or deveaged in size. There are few
destro	ans in comparison to the vehicular traffic
VONDIN	g and picking up Students at st. Dominics.
de	rease in the width of the road would
1106	e gustration and angestion to a road already
VIAC	ed for its narrow profile took The roadwal
nuanr	nore beneficial to the neighborhood than a
valk	would be Especially considering the students
ne 50	hoor do not use the roadway or future.
walk.	to get to school.
vvvvy	

SIDEWALKS AND TRAILS (WALKING AND BIKING)



2022 NW Area Mill and Overlay Project Northfield, Minnesota

4	DOADMAN	DAVENIENT	CONDITION
100	RUALIVVAY	PAVEMENT	CACHALLICIAN I

- a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed?
 Please circle one: YES NO
- 2. STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION I have observed street ponding after a significant rain. It is located at: by a For Tway standing water at Lockwood. Does your home or business have a sump pump? (address Yes or No If yes, would you be interested in a sump line extended beyond the curb to hook your sump pump discharge to? Yes or ___ No 3. SANITARY SEWER We have not experienced any problems with our sanitary sewer service. We have experienced problems with our sanitary sewer service (address WATERMAIN We have not experienced any problems with our water service. We have experienced problems with our water service (address

			G AND BIKING) re missing that ne	ed to be adde	ed to the project		
	provide location						
	RAL COMMENTS		IS uld like to be cons	idered as a pa	art of these impro	vements:	
FI	you	Nais	Quest	(op)	Planse	, con	lact
me	cut						
	7/14/	21	1				
/	7/14/	71					
	7/14/	71					
	7/14/	71					



2022 NW Area Mill and Overlay Project Northfield, Minnesota

a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed? Please circle one: YES NO	
2. STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION	
I have observed street ponding after a significant rain. It is located at:	
I have observed areas of erosion along the boulevard at:	
Does your home or business have a sump pump? (address).
If yes, would you be interested in a sump line extended beyond the curb to hook your sump pump diYes orNo	scharge to?
3. SANITARY SEWER We have not experienced any problems with our sanitary sewer service. We have experienced problems with our sanitary sewer service (address),
4. WATERMAIN	
We have not experienced any problems with our water service. We have experienced problems with our water service (address).

Are	SIDEWALKS AND TRAILS (WALKING AND BIKING)
, 110	there sidewalks or trails that you believe are missing that need to be added to the project
	Yes or No
If Ye	s, please provide location
-	
_	
_	
riea	on offer any additional information you would like to be considered as a next of these incomes to
	se offer any additional information you would like to be considered as a part of these improvements:
	se offer any additional information you would like to be considered as a part of these improvements:
	se offer any additional information you would like to be considered as a part of these improvements:
	se offer any additional information you would like to be considered as a part of these improvements:
	se offer any additional information you would like to be considered as a part of these improvements:
	se offer any additional information you would like to be considered as a part of these improvements:
	se offer any additional information you would like to be considered as a part of these improvements:
	se offer any additional information you would like to be considered as a part of these improvements:
	se offer any additional information you would like to be considered as a part of these improvements:
	se offer any additional information you would like to be considered as a part of these improvements:
	se offer any additional information you would like to be considered as a part of these improvements:
	se offer any additional information you would like to be considered as a part of these improvements:
	se offer any additional information you would like to be considered as a part of these improvements:
	se offer any additional information you would like to be considered as a part of these improvements:
	se offer any additional information you would like to be considered as a part of these improvements:
	se offer any additional information you would like to be considered as a part of these improvements:
	se offer any additional information you would like to be considered as a part of these improvements:



ROADWAY PAVEMENT CONDITION

1.

PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

 Do you feel the pavement surface has deteriorated to the point it needs to be fixed? Please circle one: YES NO 	
2. STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION	
I have observed street ponding after a significant rain. It is located at:	
1) SE section Manitor Greenvale	
I have observed areas of erosion along the boulevard at:	
Does your home or business have a sump pump? (address).
<u> </u>	
If yes, would you be interested in a sump line extended beyond the curb to hook your sump pump discha	rge to?
Yes or _X_No	
3. SANITARY SEWER	
We have not experienced any problems with our sanitary sewer service.),
4. WATERMAIN	
We have not experienced any problems with our water serviceWe have experienced problems with our water service (address	i.

5.	SIDEWALKS AND TRAILS (WALKING AND BIKING)
Are th	ere sidewalks or trails that you believe are missing that need to be added to the project
	es orNo
	please provide location
11 100	picase provide location
'lease	offer any additional information you would like to be considered as a part of these improvements: Re: Sidewalle Highland -> Vanhoe
	Currently there is a "field" Sign on the NW corner of Ivanhor Highland Intersection. Its a tricky spot. If there is going to be a sidewalk / cross walk at the EAST side of that intersection, A field or stop sign, should also be placed at.
	the NEw corner of Highland vanhoe serving Highland vanhoe serving Highland stoppied we don't want saldow pedestrians
	aptions caught in the mindle
	Highland w Jof yeld conflicts
	Crewing point
	2
	2
	•
	•



2022 NW Area Mill and Overlay Project Northfield, Minnesota

1.	a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed? Please circle one: YES NO	
0	STORM SEWED, STORM WATER PRAINAGE AND SURFACE EDGGEN	
2.	STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION	
-	_I have observed street ponding after a significant rain. It is located at:	
	I have observed areas of erosion along the boulevard at:	
	s your home or business have a sump pump? (address).
If yes	s, would you be interested in a sump line extended beyond the curb to hook your sump pump o	lischarge to?
	Yes orNo	
3.	SANITARY SEWER	
X	We have not experienced any problems with our sanitary sewer serviceWe have experienced problems with our sanitary sewer service (address	_
4.	WATERMAIN	
X	We have not experienced any problems with our water service.	
).

5. SIDEWALKS AND TRAILS (WALKING AND BIKING)	
Are there sidewalks or trails that you believe are missing that need to be added to the project	
Yes or X No	
If Yes, please provide location	
Please make available any studies about traffin and pedestrian w	
truse muse wallable any studies about traffic and pedistrian w	sage.
	-
need for a sidewalk was not significant. Few children walk through the neighborhood to get to school, and at that time of day tenffer is light. When I spoke at the city council meeting 2 years ago, I that for 2 weeks I counted car's and children. On the corner of and thighland there averaged 5 children and 2 cars. Thus, this is high-risk, unsafe intersection 70% of the traffic is neighborhood. It would be good to know if truffic studies have been done meeting 2 years ago. This was mentioned as important by the residuality order to document the need for sidewalks.	very medioned Evaphoe pot a pot a pol only. Since that idents
The proposed sidewalk cuts one of the residents' yards - it appears to halfway through the front yard and then forms a crossing. This is the least, an odd and even unsightly plan. A better plan would hapedestrians cross from Manitou to 720 Highland (at the Stop sign and then cross to 718 Highland (at the yield sign).	is to say
While I don't want a sidewalk. I see that there could be an increased as a result of the Paulsen development. Decisions about the High Sidewalk should wait until specific plans are made for this area.	land Muan he



2022 NW Area Mill and Overlay Project Northfield, Minnesota

1.	a. Do you feel the pavement su		riorated to the point it	needs to be fixed?	
	Please circle one:	YES	NO	Where	7
2.	STORM SEWER, STORM WATE	ER DRAINAGE	AND SURFACE ER	OSION	
X	have observed street ponding afte	r a significant ra	ain. It is located at:		
IN	dersection of High Can	d and Mo	nitou		
	have observed areas of erosion al				
Does	our home or business have a sump	numn? (addre	99		1
	es or \times No	pump: (addic	00		
				i and a second and	
If yes,	would you be interested in a sump	line extended b	eyond the curb to ho	ok your sump pump d	ischarge to?
Y	es orNo				
3.	SANITARY SEWER				
	We have not experienced any probl We have experienced problems with).
4.	WATERMAIN				
	Ne have not experienced any probl Ne have experienced problems with).

are there sidewalks or	AND TRAILS (WALKING AND BIKING) rails that you believe are missing that need to be added to the project
	이 집에 들어가는 어느 이 아무리 보는 아이들이 아니라 아이들이 아니다.
Yes or _X_No	
f Yes, please provide lo	ocation
	MMENTS / QUESTIONS
ease offer any addition Ve live at o the school p i) If the Part of the eas	nal information you would like to be considered as a part of these improvements: We understand the plan to connect the sidewalk on Maniton ath on Ivanhoe. However, whom Ivanhoe project is approved, would an extension of thighland Ave.
ease offer any addition We live at the school of I) If the Part to the eas Side walk	al information you would like to be considered as a part of these improvements: We understand the plan to connect the sidewalk on Maniform ath on Ivanhoe. However, whom woods project is approved, would an extension of thighland Ave. I have an impact on which side of thighland should have the
ease offer any addition Ve live at the school of 1) If the fact to the eas 3 de walk 2) We don't it to the eas a not sim	Meunderstand the plan to connect the sidewalk on Maniformation on Ivanhoe. However, whom Woods project is approved, would an extension of thighland Ave. I have an impact on which side of Highland should have the Row where stop signs will be located if Highland is extended
ease offer any addition Ve live at the school of i) If the Part to the eas side walk 2) We don't i to the eas crossing 3) If the part to the eas	Raw where stop signs will be located if Highland is extended st, because the Highland / Maniton / Lyanhoe the Highland / Maniton / Maniton Woods project is approved, which side of Highland should have the have an impact on which side of Highland should have the fit because the Highland / Maniton / I yanhoe intersection of the Highland / Maniton / I yanhoe intersection ple. But I seems safest to have the sidewalk / street located at a stop sign.
ease offer any addition We live at the school of The fact to the eas Side walk 2) We don't it to the ea so not sim crossing 3) If the ca sidewalk be painted That won and they	Reunderstand the plan to connect the sidewalk on Maniton at a on Ivanhoe. However, whom Woods project is approved, would an extension of thighland Ave. I have an impact on which side of thighland should have the three an impact on which side of thighland should have the three the stop signs will be tocated if thighland is extended st, be cause the thighland / Maniton / Ivanhoe intersection ple. But I seems safest to have the sidewalk / street tocated at a stop sign. Than remains to have the sidewalk on our property, crossing st side of Ivanhoe, we suggest considering their stop at or nearer our property line. The rosswalk could at a shight diagonal to the east side of Ivanhoe, and a shight diagonal to the middle of that intersection will probably walk on that path any walk. This would
ease offer any addition We live at to the school of I) If the Part to the eas Sidewalk 2) We don't i to the ea is not sim crossing 3) If the parte that won and they	Reunderstand the plan to connect the sidewalk on Maniton ath on Ivanhoe. However, whom Woods project is approved, would an extension of thighland Ave. I have an impact on which side of thichland should have the three an impact on which side of thichland should have the three the thighland / Maniton / Ivanhoe intersection ple. But I seems safest to have the sidewalk / street located of a stop sign. Than remains to have the sidewalk on our property, crossing st side of Ivanhoe, we single stop at or neaver our property line. The crosswalk could be a slight diagonal to the middle of that intersection led still keep kide, out of the middle of that intersection.



2022 NW Area Mill and Overlay Project Northfield, Minnesota

1.	ROADWAY PAVEMENT CONDITION
	a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed?
	Please circle one: YES (NO)
2.	STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION
X	I house who several attractions of the section of t
1	I have observed street ponding after a significant rain. It is located at:
- 1	ntersection of Lincoln Pirkury and Lethop Dine (westend)
	I have observed areas of erosion along the boulevard at:
_	
Does	your home or business have a sump pump? (address).
Xx	es orNo
1	
17	would you be interested in a sump line extended beyond the curb to hook your sump pump discharge to?
X	es orNo
3.	SANITARY SEWER
X	We have not experienced any problems with our sanitary sewer service.
	We have experienced problems with our sanitary sewer service (address)
4.	WATERMAIN
X	We have not experienced any problems with our water service.
	We have experienced problems with our water service (address).

5. SIDEWALKS AND TRAILS (WALKING AND BIKING)
Are there sidewalks or trails that you believe are missing that need to be added to the project
Yes or No
If Yes, please provide location
None speatically but I'm never apposed to mure walking an biking trails
in Matheigla
Please offer any additional information you would like to be considered as a part of these improvements:



PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

Do you feel the pavement surface has de Please circle one: YES	eteriorated to the point it needs to be fixed?	
STORM SEWER, STORM WATER DRAINAGE	GE AND SURFACE EROSION	
X I have observed street ponding after a significant	t rain. It is located at:	
South corner of Quie Ln and Freed	dom Ct.	
I have observed areas of erosion along the boule	evard at:	
Does your home or business have a sump pump? (add	dress)	
X Yes or No		
If yes, would you be interested in a sump line extended	beyond the curb to hook your sump pump discharge	to?
Yes or _X No		
3. SANITARY SEWER		
X We have not experienced any problems with our We have experienced problems with our sanitary	r sanitary sewer service. y sewer service (address).
4. WATERMAIN		
We have not experienced any problems with our We have experienced problems with our water s	r water service. service (address).	



2022 NW Area Mill and Overlay Project Northfield, Minnesota

1.	ROADWAY PAVEMENT CONDITION a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed? Please circle one: YES NO
2.	STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION
_	_I have observed street ponding after a significant rain. It is located at:
_	I have observed areas of erosion along the boulevard at:
10	your home or business have a sump pump? (address
If yes	yes or X No
3.	SANITARY SEWER _We have not experienced any problems with our sanitary sewer service. We have experienced problems with our sanitary sewer service (address).
4. X	WATERMAIN We have not experienced any problems with our water service.
-	We have experienced any problems with our water service. We have experienced problems with our water service (address

SIDEWALKS AND TRAILS (WALKING AND BIKING)
re sidewalks or trails that you believe are missing that need to be added to the project
s or X No
please provide location
offer any additional information you would like to be considered as a part of these improvements: NE feel very strongly that any plans for this should of destroy any Trees along three Parkway. The curvert boulevore peartity and has minimal traffic making the street wider here seems be a waste of money + would destroy much of the beauty of Neighborhood.



2022 NW Area Mill and Overlay Project Northfield, Minnesota

1.	ROADWAY PAVEMENT CONDITION
	 Do you feel the pavement surface has deteriorated to the point it needs to be fixed? Please circle one: YES NO
2.	STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION
	_I have observed street ponding after a significant rain. It is located at:
	_l have observed areas of erosion along the boulevard at:
Doe	s your home or business have a sump pump? (address).
	_Yes or No
If ye	s, would you be interested in a sump line extended beyond the curb to hook your sump pump discharge to?
_	Yes or No
3.	SANITARY SEWER
X	We have not experienced any problems with our sanitary sewer serviceWe have experienced problems with our sanitary sewer service (address
4.	WATERMAIN
X	_We have not experienced any problems with our water service.

5.	SIDEWALKS AND TRAILS (WALKING AND BIKING)
Are ther	e sidewalks or trails that you believe are missing that need to be added to the project
X _{Ye}	s orNo
If Yes, p	lease provide location
Ple Hi=	land and himsoln
-Wa	(kers some from both directions
-	
_	
-	
-	
-	
	GENERAL COMMENTS / QUESTIONS ffer any additional information you would like to be considered as a part of these improvements:
	not any additional information you would like to be considered as a part of these improvements.
-	
-	



PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

a. Do you feel the pavement success as deteriorated to the point it needs to be fixed? Please circle one: NO	
2. STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION	
1 have observed street ponding after a significant rain. It is located at:	1.14
in fant of our hense-	1 4man
I have observed street ponding after a significant rain. It is located at: IN funt of our world— I have observed areas of erosion along the boulevard at: I have observed areas of erosion along the boulevard at:	U days
I have observed areas of erosion along the boulevard at:	4. ago
Descriptions of huginoss have a sumo numn? (address	
Does your home or business have a sump pump? (address	
XYes orNo	
If yes, would you be interested in a sump line extended beyond the curb to hook your sump pump discharge to? Yes or No _ We would want to undustand if there is a cost Ond what it would entail So this is a depends (CS)	to Uni)
3. SANITARY SEWER	
We have not experienced any problems with our sanitary sewer service. We have experienced problems with our sanitary sewer service (address)	
. WATERMAIN	
We have not experienced any problems with our water service. We have experienced problems with our water service (address).	
- We flate expense.	

5. SIDEWALKS AND TRAILS (WALKING AND BIKING) Are there sidewalks or trails that you believe are missing that need to be added to the project Yes or No Why are you thinking of adding a bike parth on If Yes, please provide location North Ave? It would be term ble to loose all of the first of your and the street. Please the parth on the street of your and the street. Please of North Ave? It would be the project and the project of your and the street. Please of North Ave? It would be term ble to loose all of the project of your and the street.
6. GENERAL COMMENTS / QUESTIONS Please offer any additional information you would like to be considered as a part of these improvements: The Caten Vajin right in funt of our house should be fewlund of the statement of the sta
Also-the man have cover hard a son rubbar top- it icept coming off. The spikes are a hazard to car tires.

-

-



1

PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

	Do you feel the pavement Please circle one:	t surface has det YES	eriorated to the point	it needs to be fixed?	
2.	STORM SEWER, STORM WA	ATER DRAINAG	E AND SURFACE EF	ROSION	
NO	have observed street ponding a	ifter a significant	rain. It is located at:		
$\overline{\mathcal{W}}$	have observed areas of erosion	along the boule	vard at:		
1	our(home)or business have a su	mp pump? (addi	ress).
If yes, v	would you be interested in a sum	np line extended	beyond the curb to ho	ook your sump pump o	discharge to?
3.	SANITARY SEWER				
	Ve have not experienced any pro Ve have experienced problems v),
4.	WATERMAIN				
W	le have not experienced any pro le have experienced problems v	oblems with our with our with our water se	water service. & & (c rvice (address	pt costs mo	re -).

Yes please	No provide location				
res, please	provide location				
ease offer a	mproviments C	ost Money effective to Lateral American	Axen in Axen i	s paid	indsertly as a home
don't	ed Pleas Th	ve mon	Mely No.	Thank u	cesay
			E 2		



1.

PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

The City values input from residents who live along the project corridor as you have first-hand knowledge of how the streets and utilities function. Your comments / concerns will assist us during the preliminary design and layout of the project. We encourage you to take a few minutes to fill out the following questionnaire. Completed questionnaires can be collected at the Neighborhood Meeting, emailed to Sean.Simonson@ci.northfield.mn.us or dropped off at the Engineering Office located at Northfield City Hall, 801 Washington Street.

Do you feel the pavement surface has deteriorated to the point it needs to be fixed?

Please circle one: YES NO	
2. STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION	
✓ I have observed street ponding after a significant rain. It is located at:	
Driveway approach; but a getter has sunt, buest side of gutter need to be repair. Rain water down nature smooth. Sidewach: lity of Morthfreed Crase I have observed areas of erosion along the boulevard at: my sidewach to loner the height. East Section needs to be replaced to low. I have	· k
Does your home or business have a sump pump? (address The side walk in the bestloand ha	
Yes or XNO when people come in winter they have to go to the	
If yes, would you be interested in a sump line extended beyond the curb to hook your sump pump discharge to? register divise Yes or	7
3. SANITARY SEWER	
We have not experienced any problems with our sanitary sewer service. We have experienced problems with our sanitary sewer service (address).	
4. WATERMAIN	
We have not experienced any problems with our water service. X We have experienced problems with our water service (address).	
City was up to cheel it, yes we have low water pressure, They found out.	
Mon. July 12 8 pm wrater Justice was low.	

5.	SIDEWALKS AND TRAILS (WALKING AND BIKING)
Are there	sidewalks or trails that you believe are missing that need to be added to the project
	orNo
res, pie	ase provide location
. (ENERAL COMMENTS / QUESTIONS
	ENERAL COMMENTS / QUESTIONS er any additional information you would like to be considered as a part of these improvements:



We have experienced problems with our water service (address

PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

1.	a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed? Please circle one: YES NO
2.	STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION
-	_I have observed street ponding after a significant rain. It is located at:
_	_I have observed areas of erosion along the boulevard at:
Does If yes	yes or XNo - We have considered XBnt one neighbor directly to one east does a uses it regular one east does a uses it regular one become the basement still floods on occasion of the basement still floods on occasion of the basement still floods on occasion of the curb to hook your sump pump discharge to?
-	Yes orNo
3. 	SANITARY SEWER _We have not experienced any problems with our sanitary sewer serviceWe have experienced problems with our sanitary sewer service (address).
4.	WATERMAIN
X	_We have not experienced any problems with our water service.

5.	SIDEWALKS AND TRAILS (WALKING AND BIKING) re sidewalks or trails that you believe are missing that peed to be added to the project.
	re sidewalks or trails that you believe are missing that need to be added to the project of a leady showing but want to give support!
	please provide location
	Just on Ivanhoe Highland where I see one is planned.
	Thank you!!
5.	GENERAL COMMENTS / QUESTIONS
ease o	offer any additional information you would like to be considered as a part of these improvements:
P	LEASE don't remove any trees! Especially on
	St. Dlat Avenue.
2) 72	like lanes on St. Olaf Ave. Yes, please, but would
0	my like to see a time like lane, like this:
	B Please no shared bike lanes.
	K K F
	11 '11 '11 '11 '11 '11 '11 '11 '11 '11




2022 NW Area Mill and Overlay Project Northfield, Minnesota

1.	ROADWAY PAVEMENT CONDITION a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed Please circle one: YES NO	ed?
2.	STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION (elger's crav's 1 co. I have observed street bonding after a significant rain. It is located at:	
	I have observed areas of erosion along the boulevard at:	
_ <	s your home or business have a sump pump? (address or No s, would you be interested in a sump line extended beyond the curb to hook your sump put Yes or No	mp discharge to?
3.	SANITARY SEWER	
-	We have not experienced any problems with our sanitary sewer service. We have experienced problems with our sanitary sewer service (address).
4.	WATERMAIN	
K	We have not experienced any problems with our water service. We have experienced problems with our water service (address).

5.	SIDEWALKS AND TRAILS (WALKING AND BIKING)	
Are the	ere sidewalks or trails that you believe are missing that need to be added to the project	4
Y	es orNo	
If Yes,	, please provide location	4
: 	removed for theyonly slow movement and consume enmergy Remove t at Linden and Greenvale, and the east-west stop sign at Greenval	he stop
	There is a hell of a sag in Ivanhor at about 305where the storm pipe was exhumed about 5 years ago and has since sagged.	
	roidiscuss these important improvements.	
	# # # # # # # # # # # # # # # # # # #	7
Please	e offer any additional information you would like to be considered as a part of these improvements:	Ξ

2

49.2







2022 NW Area Mill and Overlay Project Northfield, Minnesota

1.	ROADWAY PAVEMENT CONDITION a. Do you feel the pavement surface has deteriorated to the point it needs to be Please circle one: YES NO	pe fixed?
2.	STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION	
	I have observed street ponding after a significant rain. It is located at:	
X	I have observed areas of erosion along the boulevard at:	
Does	your home or business have a sump pump? (address).
XY	'es orNo	
If yes,	would you be interested in a sump line extended beyond the curb to hook your sun	np pump discharge to?
Y	es or _ No perhapo- Need mure information	
3.	SANITARY SEWER	
	We have not experienced any problems with our sanitary sewer service. We have experienced problems with our sanitary sewer service (address).
4.	WATERMAIN	
	We have not experienced any problems with our water service. We have experienced problems with our water service (address).

5. SIDEWALKS AND TRAILS (WALKING AND BIKING)
Are there sidewalks or trails that you believe are missing that need to be added to the project
✓ Yes or No
If Yes, please provide location
asphalt wolkway between Ivanhoe Ave and Lathrop Dr woods repair due to tree rook buckling paths
GENERAL COMMENTS / QUESTIONS Please offer any additional information you would like to be considered as a part of these improvements:
Like to know plans for a sidewalk along Juniper Ave wo on south side of street.



PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed? Please circle one: YES NO
2. STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION
X_I have observed street ponding after a significant rain. It is located at:
St Olaf & Manton (NW corner), top of Will near Madison
XI have observed areas of erosion along the boulevard at:
Fire hydrant value between 910-1000 st. Olaf (lightpole across from Mailison)
Does your home or business have a sump pump? (address).
X_Yes orNo
If yes, would you be interested in a sump line extended beyond the curb to hook your sump pump discharge to?
Yes or _K_No
3. SANITARY SEWER
We have not experienced any problems with our sanitary sewer serviceWe have experienced problems with our sanitary sewer service (address).
4. WATERMAIN
We have not experienced any problems with our water serviceWe have experienced problems with our water service (address).

Please offer any additional information you would like to be considered as a part of these improvements:
If Yes, please provide location the ppy to see the stdewalke and troil work in the project GENERAL COMMENTS / QUESTIONS Please offer any additional information you would like to be considered as a part of these improvements:
If Yes, please provide location the ppy to seve the stelemathe and troit work in the project GENERAL COMMENTS / QUESTIONS Please offer any additional information you would like to be considered as a part of these improvements:
6. GENERAL COMMENTS / QUESTIONS Please offer any additional information you would like to be considered as a part of these improvements:
Please offer any additional information you would like to be considered as a part of these improvements:
Please offer any additional information you would like to be considered as a part of these improvements:
Please offer any additional information you would like to be considered as a part of these improvements:
Please offer any additional information you would like to be considered as a part of these improvements:
Please offer any additional information you would like to be considered as a part of these improvements:
There are low sorts and heured sichewalk slobs at various locations along st. Olat Ase
There are water value issues (low spots, loose cover etc.) in various locations along St. Olaf Ave
- sagging pavement near Linden - valve cap clanks and occasionally flops on valve at St. Olat EnMadison - have to Elyo it over 2-3 times per month



PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

	a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed Please circle one: NO NO	ed?
2.	STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION	
X	I have observed street ponding after a significant rain. It is located at:	
	woodland Tr. and Greenleaf Ct.	
X	I have observed areas of erosion along the boulevard at: West entrance onto Woodland Tr. from North	Ave.
	your home or business have a sump pump? (address).
41.10	would you be interested in a sump line extended beyond the curb to hook your sump pures or No Perhaps - need more info	ump discharge to?
3.	SANITARY SEWER	
	We have not experienced any problems with our sanitary sewer service. We have experienced problems with our sanitary sewer service (address).
	WATERMAIN We have not experienced any problems with our water service. We have experienced problems with our water service (address	- Y

5. SIDEWALKS AND TRAILS (WALKING AND BIKING)	
are there sidewalks or trails that you believe are missing that need to be added to the project	
Yes or No	
f Yes, please provide location	
lease offer any additional information you would like to be considered as a part of these impro	1
we don't need another sidewalk or trail.	
Tye and heed another stackage of that.	
ST. OIAR AVE - leave Blvd. Trees there sidewalks - and they are the "trails,"	- we don't went more
One of the beautifying aspects of a new	1
Vendarine Decina trass and even the street is	mt sul
landscape, Deing trees arch over the street in	Mot only
	0
salisting to the one, they provide shale, improves	
satisfying to the eye, they provide shale, improves	air quality, and
provide a place for nature to survive (birds, mona	air quality, and
	air quality, and



2022 NW Area Mill and Overlay Project Northfield, Minnesota

	a. Do you feel the pavement surface has deteriorated to the po	pint it needs to be fixed?	
	AREAS ALREADY ON 20,	22 MAP!	
2.	STORM SEWER, STORM WATER DRAINAGE AND SURFACE	EROSION	
! h	ave observed street ponding after a significant rain. It is located	at:	
(h	ave observed areas of erosion along the boulevard at:		
	ur home or business have a sump pump? (address).
Yes	orNo		
	ould you be interested in a sump line extended beyond the curb to or X No	o hook your sump pump disc	harge to?
3.	SANITARY SEWER		
We We	have not experienced any problems with our sanitary sewer ser have experienced problems with our sanitary sewer service (ad	vice. dress),.
4.	WATERMAIN		
X We	have not experienced any problems with our water service. have experienced problems with our water service (address		1
	mave experienced problems with our water service (address).

Are there sidewalks or trails that you believe are missing that need to be added to the project
Yes or No
If Yes, please provide location
THE PATH AROUND OUR TWO PONDS @ LIBERTY PAR
13 IN DIRE NEED OF MAINTENANCE, SEVERAL LARGE
CRACKS & DEEP HOLES ARE A DIRECT HAZARD
FOR BIKERS & WALKERS/RUNNERS.
6. GENERAL COMMENTS / QUESTIONS Please offer any additional information you would like to be considered as a part of these improvements: THE SECTION OF NORTH AVE WEST PAST
THE HOSPITAL IS REALLY IN NEED OF ATTENTION!
WE TERM IT THE "ROLLER COASTER ROAD"!

SIDEWALKS AND TRAILS (WALKING AND BIKING)

5.



2022 NW Area Mill and Overlay Project Northfield, Minnesota

1.	ROADWAY PAVEMENT CONDITION a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed?
	Please circle one: YES NO
	we dord feel we were will my man to
2.	STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION TO CONTRACT OF THE STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION
X	_I have observed street ponding after a significant rain. It is located at:
= ir	Please circle one: YES NO We don't fell we are well informed enough STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION I have observed street ponding after a significant rain. It is located at: Tersection of Woodland Trail and Green eaf Ct. This creates ice in winter - very problematic I have observed areas of erosion along the boulevard at:
Does	your home or business have a sump pump? (address
X	Yes or No
If yes	would you be interested in a sump line extended beyond the curb to hook your sump pump discharge to? Yes or X No of our house.
3.	SANITARY SEWER
V	
4.	WATERMAIN
V	We have not experienced any problems with our water service.
	We have experienced problems with our water service (address).

SIDEWALK					
there sidewalks	or trails that you beli	eve are missin	ng that need to	be added to the project	
_Yes or _X	No				
es, please provide	e location				
	COMMENTS / QUES				
		u would like to		as a part of these impr	rovements:
		u would like to	be considered	as a part of these impr	rovements:
		u would like to		as a part of these impr	rovements:
		u would like to		as a part of these impr	rovements:
		u would like to		as a part of these impr	rovements:
		u would like to		as a part of these impr	rovements:
		u would like to		as a part of these impr	rovements:
		u would like to		as a part of these impr	rovements:
		u would like to	0	as a part of these impr	rovements:
		u would like to	0	as a part of these impr	rovements:
		u would like to	0	as a part of these impr	rovements:
		u would like to	0	as a part of these impr	rovements:
		u would like to	0	as a part of these impr	rovements:
		u would like to	0	as a part of these impr	rovements:



PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

a. Do you feel the pavement surface has deteriorated to the point it needs to Please circle one: YES NO	be fixed?
2. STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION	
I have observed street ponding after a significant rain. It is located at:	
I have observed areas of erosion along the boulevard at:	
Does your home or business have a sump pump? (address	
If yes, would you be interested in a sump line extended beyond the curb to hook your su Yes orNo "no" not applicable	ump pump discharge to?
3. SANITARY SEWER	
We have not experienced any problems with our sanitary sewer service. We have experienced problems with our sanitary sewer service (address	Dien the years cleaned twice from house to connection at steet.
4. WATERMAIN	house to conhection.
We have not experienced any problems with our water service. We have experienced problems with our water service (address	

5. SIDE	VALKS AND TRAIL	S (WALKING AND B	IKING)			710
Are there sidev	alks or trails that yo	ou believe are missing	that need to be added to	the project		14
res or	No					
f Yes, please p						
(ouside)	extending	side walks	along summ	on field to	Carrie	Valla 7
OR	B. Ke path	Gon children	٧.		Q u uu	outey F
			8			
	. COMMENTS / QU					
			considered as a part of the	ese improvements:		
			considered as a part of the	ese improvements:		
			considered as a part of the	ese improvements:		
			considered as a part of the	ese improvements:		
			considered as a part of the	ese improvements:		
			considered as a part of the	ese improvements:		
			considered as a part of the	ese improvements:		
			considered as a part of the	ese improvements:		
			considered as a part of the	ese improvements:		
			considered as a part of the	ese improvements:		
			considered as a part of the	ese improvements:		
			considered as a part of the	ese improvements:		

- HELL-



2022 NW Area Mill and Overlay Project Northfield, Minnesota

1.	ROADWAY PAVEMENT CONDITION a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed?
	Please circle one: YES NO There are some places around drain/sewer covers that need attention
2.	STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION
	_I have observed street ponding after a significant rain. It is located at:
	_I have observed areas of erosion along the boulevard at:
	_ Mare executed areas of creation along the bodic value.
	your home or business have a sump pump? (address). Yes or No
	would you be interested in a sump line extended beyond the curb to hook your sump pump discharge to?
XX	Yes orNo Sometimes our sump pump runs before the frost has gone out. Would it accept water during the winter months before temps move above freezing?
3.	SANITARY SEWER
XX	We have not experienced any problems with our sanitary sewer service. We have experienced problems with our sanitary sewer service (address).
4.	WATERMAIN
XX	We have not experienced any problems with our water service. We have experienced problems with our water service (address

_Yes or _	XX No
es, please pr	ovide location
GENER	AL COMMENTS / QUESTIONS
ease offer any	additional information you would like to be considered as a part of these improvements:
ease offer any	additional information you would like to be considered as a part of these improvements: and behind 1101 Woodland trail that has a drainage line to the storm sewer system. Exploration by the
ease offer any There is a por city in spring table in the a	additional information you would like to be considered as a part of these improvements: and behind 1101 Woodland trail that has a drainage line to the storm sewer system. Exploration by the 2020 found that the line was not draining properly and the pond level and general level of the water rea were unusually high. Our home experienced a great deal of ponding in our front and back yard
There is a porcity in spring table in the a	additional information you would like to be considered as a part of these improvements: and behind 1101 Woodland trail that has a drainage line to the storm sewer system. Exploration by the 2020 found that the line was not draining properly and the pond level and general level of the water rea were unusually high. Our home experienced a great deal of ponding in our front and back yard spring 2020 as well as the spring seasons of the previous three years. Our sump pump ran most of the
There is a porcity in spring table in the a during time from Mawould ask that	additional information you would like to be considered as a part of these improvements: and behind 1101 Woodland trail that has a drainage line to the storm sewer system. Exploration by the 2020 found that the line was not draining properly and the pond level and general level of the water rea were unusually high. Our home experienced a great deal of ponding in our front and back yard spring 2020 as well as the spring seasons of the previous three years. Our sump pump ran most of the trich until June in 2020. I'm not sure what the current status of the drain line from the pond is, but I at the city include any necessary improvements or repairs to manage the surface water levels and water
There is a porcity in spring table in the a during time from Mawould ask that table levels in	additional information you would like to be considered as a part of these improvements: and behind 1101 Woodland trail that has a drainage line to the storm sewer system. Exploration by the 2020 found that the line was not draining properly and the pond level and general level of the water rea were unusually high. Our home experienced a great deal of ponding in our front and back yard spring 2020 as well as the spring seasons of the previous three years. Our sump pump ran most of the prochuntil June in 2020. I'm not sure what the current status of the drain line from the pond is, but I at the city include any necessary improvements or repairs to manage the surface water levels and water the pond and property addresses in this general southeast corner of Woodland Trail. We have had
There is a porcity in spring table in the a during time from Mawould ask that table levels in one large oak	additional information you would like to be considered as a part of these improvements: and behind 1101 Woodland trail that has a drainage line to the storm sewer system. Exploration by the 2020 found that the line was not draining properly and the pond level and general level of the water rea were unusually high. Our home experienced a great deal of ponding in our front and back yard spring 2020 as well as the spring seasons of the previous three years. Our sump pump ran most of the arch until June in 2020. I'm not sure what the current status of the drain line from the pond is, but I set the city include any necessary improvements or repairs to manage the surface water levels and water the pond and property addresses in this general southeast corner of Woodland Trail. We have had die in our back yard and have had it removed. The tree specialists thought the high water levels in the
There is a porcity in spring table in the a during time from Mawould ask that table levels in one large oak	additional information you would like to be considered as a part of these improvements: and behind 1101 Woodland trail that has a drainage line to the storm sewer system. Exploration by the 2020 found that the line was not draining properly and the pond level and general level of the water rea were unusually high. Our home experienced a great deal of ponding in our front and back yard spring 2020 as well as the spring seasons of the previous three years. Our sump pump ran most of the prochuntil June in 2020. I'm not sure what the current status of the drain line from the pond is, but I at the city include any necessary improvements or repairs to manage the surface water levels and water the pond and property addresses in this general southeast corner of Woodland Trail. We have had
There is a porcity in spring table in the a during time from Mawould ask that table levels in one large oak	additional information you would like to be considered as a part of these improvements: and behind 1101 Woodland trail that has a drainage line to the storm sewer system. Exploration by the 2020 found that the line was not draining properly and the pond level and general level of the water rea were unusually high. Our home experienced a great deal of ponding in our front and back yard spring 2020 as well as the spring seasons of the previous three years. Our sump pump ran most of the arch until June in 2020. I'm not sure what the current status of the drain line from the pond is, but I set the city include any necessary improvements or repairs to manage the surface water levels and water the pond and property addresses in this general southeast corner of Woodland Trail. We have had die in our back yard and have had it removed. The tree specialists thought the high water levels in the
There is a porcity in spring table in the a during time from Mawould ask that table levels in one large oak	additional information you would like to be considered as a part of these improvements: and behind 1101 Woodland trail that has a drainage line to the storm sewer system. Exploration by the 2020 found that the line was not draining properly and the pond level and general level of the water rea were unusually high. Our home experienced a great deal of ponding in our front and back yard spring 2020 as well as the spring seasons of the previous three years. Our sump pump ran most of the arch until June in 2020. I'm not sure what the current status of the drain line from the pond is, but I set the city include any necessary improvements or repairs to manage the surface water levels and water the pond and property addresses in this general southeast corner of Woodland Trail. We have had die in our back yard and have had it removed. The tree specialists thought the high water levels in the
There is a porcity in spring table in the a during time from Mawould ask that table levels in one large oak	additional information you would like to be considered as a part of these improvements: and behind 1101 Woodland trail that has a drainage line to the storm sewer system. Exploration by the 2020 found that the line was not draining properly and the pond level and general level of the water rea were unusually high. Our home experienced a great deal of ponding in our front and back yard spring 2020 as well as the spring seasons of the previous three years. Our sump pump ran most of the arch until June in 2020. I'm not sure what the current status of the drain line from the pond is, but I set the city include any necessary improvements or repairs to manage the surface water levels and water the pond and property addresses in this general southeast corner of Woodland Trail. We have had die in our back yard and have had it removed. The tree specialists thought the high water levels in the
There is a porcity in spring table in the a during time from Mawould ask that table levels in one large oak	additional information you would like to be considered as a part of these improvements: and behind 1101 Woodland trail that has a drainage line to the storm sewer system. Exploration by the 2020 found that the line was not draining properly and the pond level and general level of the water rea were unusually high. Our home experienced a great deal of ponding in our front and back yard spring 2020 as well as the spring seasons of the previous three years. Our sump pump ran most of the arch until June in 2020. I'm not sure what the current status of the drain line from the pond is, but I set the city include any necessary improvements or repairs to manage the surface water levels and water the pond and property addresses in this general southeast corner of Woodland Trail. We have had die in our back yard and have had it removed. The tree specialists thought the high water levels in the
There is a porcity in spring table in the a during time from Mawould ask that table levels in one large oak	additional information you would like to be considered as a part of these improvements: and behind 1101 Woodland trail that has a drainage line to the storm sewer system. Exploration by the 2020 found that the line was not draining properly and the pond level and general level of the water rea were unusually high. Our home experienced a great deal of ponding in our front and back yard spring 2020 as well as the spring seasons of the previous three years. Our sump pump ran most of the arch until June in 2020. I'm not sure what the current status of the drain line from the pond is, but I set the city include any necessary improvements or repairs to manage the surface water levels and water the pond and property addresses in this general southeast corner of Woodland Trail. We have had die in our back yard and have had it removed. The tree specialists thought the high water levels in the
There is a porcity in spring table in the a during time from Mawould ask that table levels in one large oak	additional information you would like to be considered as a part of these improvements: and behind 1101 Woodland trail that has a drainage line to the storm sewer system. Exploration by the 2020 found that the line was not draining properly and the pond level and general level of the water rea were unusually high. Our home experienced a great deal of ponding in our front and back yard spring 2020 as well as the spring seasons of the previous three years. Our sump pump ran most of the arch until June in 2020. I'm not sure what the current status of the drain line from the pond is, but I set the city include any necessary improvements or repairs to manage the surface water levels and water the pond and property addresses in this general southeast corner of Woodland Trail. We have had die in our back yard and have had it removed. The tree specialists thought the high water levels in the
There is a porcity in spring table in the a during time from Mawould ask that table levels in one large oak	additional information you would like to be considered as a part of these improvements: and behind 1101 Woodland trail that has a drainage line to the storm sewer system. Exploration by the 2020 found that the line was not draining properly and the pond level and general level of the water rea were unusually high. Our home experienced a great deal of ponding in our front and back yard spring 2020 as well as the spring seasons of the previous three years. Our sump pump ran most of the arch until June in 2020. I'm not sure what the current status of the drain line from the pond is, but I set the city include any necessary improvements or repairs to manage the surface water levels and water the pond and property addresses in this general southeast corner of Woodland Trail. We have had die in our back yard and have had it removed. The tree specialists thought the high water levels in the



1.

PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

	a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed? Please circle one: NO
2.	STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION
_	I have observed street ponding after a significant rain. It is located at:
	I have observed areas of erosion along the boulevard at:
	your home or business have a sump pump? (address).
	es orNo
1	would you be interested in a sump line extended beyond the curb to hook your sump pump discharge to?
3.	SANITARY SEWER
	We have not experienced any problems with our sanitary sewer service. We have experienced problems with our sanitary sewer service (address).
4.	WATERMAIN
	We have not experienced any problems with our water service. We have experienced problems with our water service (address).

5. SIE	DEWALKS AND TR	1					
Are there sid	dewalks or trails tha	at you believe a	re missing that nee	d to be added to the p	roject		
yes o	r No						
f Yes, pleas	e provide location						
	NERAL COMMENT						
	any additional infor	mation you woo	uld like to be consided	ered as a part of these	of trees (F)	the propose	d trail
	any additional infor lam deeple Zoes three traffic o	mation you wou y concerne ough - The n Eveleth	uld like to be consided about the core is one name to con	destruction , nore difficulty trol (i.e. Stop S	of trees (F)	the propose	NORTH SOU
	l am deeph Zoes thre traffic o North A	mation you wol y concerne ough - Th n Eveleth Venue & bea	uld like to be consided about the sere is one no conscious Falk Av	destruction in hore difficulty trol (i.e. Stop Senue-	of trees (F) - zestuzili ign) where	the propose 1 DANGER; e Eveleth c	Noeth Sou rosses
	any additional infor Lam deeple Zoes three traffic o North As	mation you wol y concerne bugh - Th n Eveleth venue & bea tly this pro	uld like to be consided about the learning the mas NO con- comes Falk Au posed trail in	destruction in the destruction in the difficulty trol (i.e. Stop Senue-	of trees (F) - aestually ign) when ign when	the propose 1 DANGER; e Eveleth c	Noeth Sou rosses
	any additional infor Lam deeple Zoes three traffic o North As	mation you wol y concerne bugh - Th n Eveleth venue & bea tly this pro	uld like to be consided about the learning the mas NO con- comes Falk Au posed trail in	destruction in hore difficulty trol (i.e. Stop Senue-	of trees (F) - actually ign) when uned to co	the propose 1 DANGER; 2 Eveleth c nnect with	NORTH SOU MOSSES
	any additional infor	mation you wol y concerne ough - The n Eveleth venue & becomes tly this pro-	uld like to be consided about the learning the mas NO con- comes Falk Au posed trail in	destruction in the destruction in the difficulty trol (i.e. Stop Senue-	of trees (F) - autually ign) when med to co pital-	the propose 1 DANGER; 2 Eveleth c unect with unect with	NORTH SOU MOSSES
ease offer	any additional infor	mation you wou y concerne pugh - Th n Eveleth venue & bea tly this pro	uld like to be consided about the care is one or has NO consciones Falk Averages of the consideration of the control of the co	destruction in the destruction in the difficulty trol (i.e. Stop Senue-	of trees (F) - autually ign) when med to co pital-	the propose 1 DANGER; 2 Eveleth c unect with unect with unect with beca control put in (i.c.	NORTH SOU MOSSES The less of is Stop Sig) &
ease offer	Apparen Pump Hoppe	mation you wol y concerne pugh - Th n Eveleth venue & bea tly this pro	uld like to be consided about the core is one or has NO concornes Falk Autoposed trail in Southfide of	destruction in the destruction in the difficulty trol (i.e. Stop Senue-	of trees (F) - autually ign) when med to co pital-	the propose 1 DANGER; 2 Eveleth c unect with unfil & un speed contr put in (i.e. Enforced-	North Sources
ease offer	Apparen Pump Hopse To additional inform Jord deeple Goes three traffic o North An Apparen E-W traffic Pump Hopse To 1011-17 8	mation you wou y concerne pugh - Th n Eveleth venue & bea tly this pro	uld like to be consided about the care is one in the consideration of the consideration of the control of the c	destruction in the destruction in the difficulty trol (i.e. Stop Senue-	of trees (F) - aestually ign) when uned to co	the propose DANGER; E Eveleth c unect with Unfil & un Bred contr put in (i.c. Enforced- inscrtion i	NORTH SOU Prosses The Iess of is Stop Sig) & This "trail" Is more apt
ease offer	any additional infor	mation you work y concerne pugh - Th n Eveleth venue & ber tly this pro in on the	uld like to be consided about the care is one in the consideration of the consideration of the control of the c	destruction in the destruction is a destruction in the stop of the local hos	of trees (F) - aestually ign) when uned to co	the propose A DANGER; E Eveleth c unect with Unfil & un Breed contr put in (i.c. inscrtion i to fill hosp	NORTH SOU MOSSES The Iess of is Stop Sig) & This "trail" This "trail" This "trail"
ease offer	Apparen Pump Hopps Tuning	mation you would concerned bugh - The releth venue & bear that this probability this probability that probability the probability the probability that probability the probability the probability that probability the probability the	uld like to be consided about the end about the end one	destruction in the destruction is a destruction in the stop of the local hos	of trees (F) - aestually ign) when uned to co	the propose A DANGER; E Eveleth c unect with Unfil & un Breed contr put in (i.c. inscrtion i to fill hosp	NORTH SOL NORTH SOL NORTH SOL NORTH SOL NORTH SOL Stop Sig) & This "trail" This "trail" This "trail" This "trail"
ease offer	any additional infor	mation you would concerned bugh - The releth venue & bear that this probability this probability that probability the probability the probability that probability the probability the probability that probability the probability the	uld like to be consided about the care is one or has NO consciones Falk Autoposed trail is Southfide a without CT	destruction in ore difficulty trol (i.e. Stop Senue- mention is plantation in plantati	of trees (F) - aestually ign) when uned to co	the propose A DANGER; E Eveleth c unect with Unfil & un Breed contr put in (i.c. inscrtion i to fill hosp	NORTH SOU MOSSES The Iess of is Stop Sig) & This "trail" This "trail" This "trail"
ease offer	any additional infor	mation you would concerned bugh - The releth venue & bearing the first this product to the last the la	uld like to be consided about the care is one or has NO consciones Falk Autoposed trail is Southfide a without CT	destruction in ore difficulty trol (i.e. Stop Senue- mention is plantation in plantati	of trees (F) - aestually ign) when uned to co	the propose A DANGER; E Eveleth c unect with Unfil & un Breed contr put in (i.c. inscrtion i to fill hosp	NORTH SOU MOSSES The Iess of is Stop Sig) & This "trail" This "trail" This "trail"
ease offer	any additional infor	mation you would concerned bugh - The releth venue & bearing the first this product to the last the la	uld like to be consided about the care is one or has NO consciones Falk Autoposed trail is Southfide a without CT	destruction in ore difficulty trol (i.e. Stop Senue- mention is plantation in plantati	of trees (F) - aestually ign) when uned to co	the propose A DANGER; E Eveleth c unect with Unfil & un Breed contr put in (i.c. inscrtion i to fill hosp	NORTH SOU MOSSES The Stop Sig) & This "trail" This "trail" more apt ital beds or
lease offer	any additional infor	mation you would concerned bugh - The releth venue & bearing the first this product to the last the la	uld like to be consided about the care is one or has NO consciones Falk Autoposed trail is Southfide a without CT	destruction in ore difficulty trol (i.e. Stop Senue- mention is plantation in plantati	of trees (F) - actually ign) where nned to co pital-	the propose A DANGER; E Eveleth c unect with Unfil & un Breed contr put in (i.c. inscrtion i to fill hosp	NORTH SOU rosses the less of is Stop Sig) & This "trai!"

From:
To: Sean Simonson
Cc:

Subject: Project Questionnaire, 2022 NW Area Mill and Overlay Project

Date: Monday, July 26, 2021 3:01:04 PM

CAUTION: This email originated from outside of the organization.

1. ROADWAY PAVEMENT CONDITION

a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed?

Please circle one: YES

2. STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION

I have observed ponding after a significant rain. It is located at the intersection of Lincoln Parkway and Cannon Valley Drive.

Does your home or business have a sump pump?

YES.

If yes, would you be interested in a sumpline extended beyond the curb to hook your sump pump discharge to?

NO

3. SANITARY SEWER

I have not experienced any problems with our sanitary sewer service

4. WATERMAIN

I have not experienced ay problems with our water service.

5. I am not aware of sidewalks or trails that are missing that need to be added to the project.



PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

	 Do you feel the pavement surface has deteriorated to the point it needs to be fixed? Please circle one: YES NO 	
2.	STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION	
	I have observed street ponding after a significant rain. It is located at:	
_	I have observed areas of erosion along the boulevard at:	
Doe	your home or business have a sump pump? (address). 'es or No	
If ye	would you be interested in a sump line extended beyond the curb to hook your sump pump discharge to	?
3.	SANITARY SEWER	
<u>V</u>	We have not experienced any problems with our sanitary sewer service. We have experienced problems with our sanitary sewer service (address).
4.	WATERMAIN	
1	We have not experienced any problems with our water service. We have experienced problems with our water service (address).	

5.	DEWALKS AND TRAILS (WALKING AND BIKING)
Are there	idewalks or trails that you believe are missing that need to be added to the project
Vac	or <u>No</u>
If Yes, pl	se provide location
	ENERAL COMMENTS / QUESTIONS
	ENERAL COMMENTS / QUESTIONS r any additional information you would like to be considered as a part of these improvements:
	r any additional information you would like to be considered as a part of these improvements:
	r any additional information you would like to be considered as a part of these improvements:
	r any additional information you would like to be considered as a part of these improvements:
	r any additional information you would like to be considered as a part of these improvements:
	r any additional information you would like to be considered as a part of these improvements:
	r any additional information you would like to be considered as a part of these improvements:
	r any additional information you would like to be considered as a part of these improvements:
	r any additional information you would like to be considered as a part of these improvements:
	r any additional information you would like to be considered as a part of these improvements:
	r any additional information you would like to be considered as a part of these improvements:



2022 NW Area Mill and Overlay Project Northfield, Minnesota

 ROADWAY PAVEMENT CONDITION a. Do you feel the pavement surface has detejiorated to the point it needs to be fixed?
Please circle one: YES NO
2. STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION
I have observed street ponding after a significant rain. It is located at:
Various drains along Woodland Tail
have observed areas of erosion along the boulevard at:
Does your home or business have a sump pump? (address).
✓Yes orNo
If yes, would you be interested in a sump line extended beyond the curb to hook your sump pump discharge to?
√Yes orNo
3. SANITARY SEWER
We have not experienced any problems with our sanitary sewer service. We have experienced problems with our sanitary sewer service (address
4. WATERMAIN
✓ We have not experienced any problems with our water service.
We have experienced problems with our water service (address).

Are th	SIDEWALKS AND TRAILS (WALKING AND BIKING)
	ere sidewalks or trails that you believe are missing that need to be added to the project
	10명에 하는 200 전 12명이 되었다. 이 12명이 12명이 12명이 12명이 12명이 12명이 12명이 12
	es or No
If Vos	, please provide location
11 163	please provide location
	PLEASE - do not add statewalks to Woodland Trail So many beautif trees would be distroyed for so little gain.
_	many beautiful trees would be distroyed for so little gain.
_	
-	
_	
-	
-	
6. Pleas	GENERAL COMMENTS / QUESTIONS e offer any additional information you would like to be considered as a part of these improvements:
	: 선거에 대한 경우 가지에 있는 10. 이번 10. 10. 10. 10. 10. 10. 10. 10. 10. 10.



1.

PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

The City values input from residents who live along the project corridor as you have first-hand knowledge of how the streets and utilities function. Your comments / concerns will assist us during the preliminary design and layout of the project. We encourage you to take a few minutes to fill out the following questionnaire. Completed questionnaires can be collected at the Neighborhood Meeting, emailed to Sean.Simonson@ci.northfield.mn.us or dropped off at the Engineering Office located at Northfield City Hall, 801 Washington Street.

a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed?

	Please circle one: YES	
2. S	STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION	
I ha	ve observed street ponding after a significant rain. It is located at:	
I hav	ve observed areas of erosion along the boulevard at:	
The second second	home or business have a sump pump? (address or \(\sum_{No} \)	
	or No	sump pump discharge to?
We I	ANITARY SEWER have not experienced any problems with our sanitary sewer service. have experienced problems with our sanitary sewer service (address	Sorry-can't make it to meeting.
X We h	WATERMAIN have not experienced any problems with our water service. have experienced problems with our water service (address	

	that you believe are missing	that need to be added to the p	roject	
_Yes or _X No				
es, please provide locat	on			
	4			
	nformation you would like to I	be considered as a part of these		previon
there a	re no	concerns	at	thes
hime.	we wo	ned like	40	opt.
out of	payme	tas we	have	paid
r past	assism	ert.		•



2022 NW Area Mill and Overlay Project Northfield, Minnesota

1.	ROADWAY PAVEMENT CONDITION a. Do you feel the pavement surface has deteriorated to the point it needs to be to	Eved?
	Please circle one: YES (NO)	incu :
2.	STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION	
	_I have observed street ponding after a significant rain. It is located at:	
	No	
	_I have observed areas of erosion along the boulevard at:	
	No	
Does	s your home or business have a sump pump? (address_).
A	Yes orNo	
-		
	s, would you be interested in a sump line extended beyond the curb to hook your sump	pump discharge to?
_	Yes or X No	
3.	SANITARY SEWER	
X	/ We have a transferred and an architecture with a constitution of the constitution of	
	_We have not experienced any problems with our sanitary sewer serviceWe have experienced problems with our sanitary sewer service (address).
4.	WATERMAIN	
X	_We have not experienced any problems with our water service.	
	We have experienced problems with our water service (address).

	SIDEWALKS AND TRAILS (WALKING AND BIKING)
are the	e sidewalks or trails that you believe are missing that need to be added to the project
Ye	s or 📈 No
f Yes,	lease provide location
	GENERAL COMMENTS / QUESTIONS offer any additional information you would like to be considered as a part of these improvements:
	offer any additional information you would like to be considered as a part of these improvements:
	offer any additional information you would like to be considered as a part of these improvements:
	offer any additional information you would like to be considered as a part of these improvements:
S. Please	offer any additional information you would like to be considered as a part of these improvements:



2022 NW Area Mill and Overlay Project Northfield, Minnesota

1.	ROADWAY PAVEMENT CONDITION a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed?	
	Please circle one: YES (NO)	
2.	STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION	
_	I have observed street ponding after a significant rain. It is located at:	
1	_I have observed areas of erosion along the boulevard at:	
Does	your home or business have a sump pump? (address	
	yes orNo	
3.	SANITARY SEWER	
_X	_We have not experienced any problems with our sanitary sewer serviceWe have experienced problems with our sanitary sewer service (address	_).
4.	WATERMAIN	
Y	_We have not experienced any problems with our water serviceWe have experienced problems with our water service (address).	

	r trails that you believe are missing that need to be added to the project
Yes or X	
s, please provide	
s, picase provide	location
GENERAL C	
	OMMENTS / QUESTIONS
e offer any addit	
e offer any addit	OMMENTS / QUESTIONS onal information you would like to be considered as a part of these improvements:
e offer any addit	
e offer any addit	
Not ? North	onal information you would like to be considered as a part of these improvements: En favor of Any work along Ave or Woodland Trail
Not ? North	onal information you would like to be considered as a part of these improvements: En favor of Any work along Ave or Woodland Trail
Not of North That	onal information you would like to be considered as a part of these improvements: En favor of Any work along Ave or Woodland Trail Involves Removing
Not of North That	onal information you would like to be considered as a part of these improvements: En favor of Any work along Ave or Woodland Trail Involves Removing
Not of North That	onal information you would like to be considered as a part of these improvements: En favor of Any work along Ave or Woodland Trail
Not of North That	onal information you would like to be considered as a part of these improvements: En favor of Any work along Ave or Woodland Trail Involves Removing
Not of North That Exis	onal information you would like to be considered as a part of these improvements: In favor of Any Work along Ave or Woodland Trail Involves Removing Hing Trees!
Not of North That Exis	onal information you would like to be considered as a part of these improvements: En favor of Any work along Ave or Woodland Trail Involves Removing

July 22, 2011



PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

1.	ROADWAY PAVEMENT CONDITION a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed? Please circle one: YES NO
	only For MINOR REPAIRS! MILL & OVERLAY.
2.	STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION
	I have observed street ponding after a significant rain. It is located at: GREENLE AF CERRICA OF STEDIO CT. & WOODERNE AND TRAIL
_	I have observed areas of erosion along the boulevard at:
v	your home or business have a sump pump? (address
9	Yes or VNo
3.	SANITARY SEWER
	We have not experienced any problems with our sanitary sewer service. We have experienced problems with our sanitary sewer service (address).
4,	WATERMAIN
L	_We have not experienced any problems with our water serviceWe have experienced problems with our water service (address)

e there sidewalks or Yes orNo	N	FUER ON	be added to the project	TRAIL.	THIS WE
Yes, please provide k		WENES W	ORIFINAL	INTION &	THE CIT
	347 ! Use AN	ON THE	NORTH SI REET BU		ONTH DU STREET
DEF1	NITELY		EPARATE		,
AFFECT	MATU	CHARAC	Tel OF	PAVE	3564
10616	H BORLAS	ο Δ , ,	9ica - 70	e Expen	SIVE;
				-	
	MMENTS / QUESTION				order for the delication of th
ase offer any addition	nal information you wo	uld like to be considered	as a part of these improv	/ements:	
		uld like to be considered	TP AK OI	vements:	
ase offer any addition	nal information you won	uld like to be considered	TRAK OF	vements:	
ase offer any addition	nal information you won	uld like to be considered	TP AK OI	vements:	
ase offer any addition	nal information you won	uld like to be considered	TP AK OI	vements:	
ase offer any addition	nal information you won	uld like to be considered	TP AK OI	vements:	
ase offer any addition	nal information you won	uld like to be considered	TP AK OI	vements:	



2022 NW Area Mill and Overlay Project Northfield, Minnesota

1.	a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed? Please circle one: YES NO	
2.	STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION	
_	I have observed street ponding after a significant rain. It is located at:	
	I have observed areas of erosion along the boulevard at:	a.
_	es your home or business have a sump pump? (address).
ye	_Yes or No	ulconargo to .
3.	SANITARY SEWER We have not experienced any problems with our sanitary sewer service. We have experienced problems with our sanitary sewer service (address),
4.	WATERMAIN	
X	We have not experienced any problems with our water serviceWe have experienced problems with our water service (address),

5.	SIDEWALKS AND TRAILS (WALKING AND BIKING)
Are	there sidewalks or trails that you believe are missing that need to be added to the project
	Yes orNo
If Ye	s, please provide location
	In the initial plans years ago there was originally supposed to be a small tength of walley biting that the existing subwalls as trails. One connecting by the connecting to the connecting by the part walley orive. Another connecting by ildusors count to the trail and would be approxime.
6. Pleas	GENERAL COMMENTS / QUESTIONS e offer any additional information you would like to be considered as a part of these improvements: We do not need now support amplifus section of them
_	Woodfood That. The city does not have the time or
	resources to encirtain this property especially in winter. There work existing sidewalk or trail all the way from Northbriell Hospital to John Worth Pork. Please do not can be down benefit on the forth one blance blands
	for our unnecessary that. Thank you!




2022 NW Area Mill and Overlay Project Northfield, Minnesota

1. ROADWAY PAVEMENT CONDITION
a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed? Please circle one: NO
2. STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION
1 have observed street ponding after a significant rain. It is located at:
North side of Northshe west of Dubth the by North Booster Station
I have observed areas of erosion along the boulevard at:
Does your home or business have a sump pump? (address). X Yes or No
If yes, would you be interested in a sump line extended beyond the curb to hook your sump pump discharge to?
Yes or No N/A- done in 2019
3. SANITARY SEWER
We have not experienced any problems with our sanitary sewer serviceWe have experienced problems with our sanitary sewer service (address
4. WATERMAIN
We have not experienced any problems with our water service. We have experienced problems with our water service (address).

5. SIDEWALKS AND TRAILS (WALKING AND BIKING)	
Are there sidewalks or trails that you believe are missing that need to be added to the project	
Yes or $^{1}\!$	
Tes_orNo	
If Yes, please provide location	
THE PROPERTY OF THE PROPERTY O	
6. GENERAL COMMENTS / QUESTIONS Please offer any additional information you would like to be considered as a part of these improvements:	
Please offer any additional information you would like to be considered as a part of these improvements:	
Please offer any additional information you would like to be considered as a part of these improvements:	
Please offer any additional information you would like to be considered as a part of these improvements:	
Please offer any additional information you would like to be considered as a part of these improvements:	
Please offer any additional information you would like to be considered as a part of these improvements:	
Please offer any additional information you would like to be considered as a part of these improvements:	
Please offer any additional information you would like to be considered as a part of these improvements:	
Please offer any additional information you would like to be considered as a part of these improvements:	
Please offer any additional information you would like to be considered as a part of these improvements:	
Please offer any additional information you would like to be considered as a part of these improvements:	
Please offer any additional information you would like to be considered as a part of these improvements:	
Please offer any additional information you would like to be considered as a part of these improvements:	
Please offer any additional information you would like to be considered as a part of these improvements:	
Please offer any additional information you would like to be considered as a part of these improvements:	
Please offer any additional information you would like to be considered as a part of these improvements:	
Please offer any additional information you would like to be considered as a part of these improvements:	
Please offer any additional information you would like to be considered as a part of these improvements:	
Please offer any additional information you would like to be considered as a part of these improvements:	

General Comments / Questions:

- 1) Specifically as to the proposed North Ave. trail addition:
 - a. Stating the obvious, we don't want a trail addition in our yard nor do we see a need considering there's a sidewalk on the south side of the street. Do we as taxpayers have any say in this matter? (Significant cost to taxpayers.)
 - b. What is the total cost of this trail addition? Can we see the budget breakdown?
 - c. Who's requesting that this trail be added? What did your feasibility study identify as walking and biking traffic volume that necessitated adding a trail?
 - d. Subdivision plat references draining and utility easements being 10 feet in width and adjoining street lines. Please identify the trail width and where it would be located on our property.
 - e. How long has this trail addition been considered by the city and parks & rec department?
 - f. Why wasn't there proactive planning to ramp or cut curb sections for this trail when those curb sections were replaced in 2019? (An additional cost to taxpayers.)
 - g. What trees will be removed? How many in total will be removed?
 - h. Will the city be replacing trees along the property line?
 - i. Will the city offer to add the option of a privacy fence at their cost?
 - j. Who will be relocating sprinkler system lines and who bears that cost?
 - k. Will retaining walls be added in the areas that slope? Specifically, our yard slopes downward to the street.
 - I. Will we be charged any special assessments?
 - m. Looking at the property map on the Dakota County website, assuming the city has an additional easement on the "Cannon Valley Estates" parcel since the property line is indented for that subdivision plat section on the Dakota County website map. Please clarify.
- 2) North Ave. street mill and overlay
 - a. Will we be charged any special assessments?



PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

The City values input from residents who live along the project corridor as you have first-hand knowledge of how the streets and utilities function. Your comments / concerns will assist us during the preliminary design and layout of the project. We encourage you to take a few minutes to fill out the following questionnaire. Completed questionnaires can be collected at the Neighborhood Meeting, emailed to Sean.Simonson@ci.northfield.mn.us or dropped off at the Engineering Office located at Northfield City Hall, 801 Washington Street.

a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed?

Please circle one: YES NO	
2. STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION	
I have observed street ponding after a significant rain. It is located at:	
I have observed areas of erosion along the boulevard at:	
Does your home or business have a sump pump? (address_	
Yes orNo	
If yes, would you be interested in a sump line extended beyond the curb to hook your sump	pump discharge to?
Yes or K No	
3. SANITARY SEWER	
We have not experienced any problems with our sanitary sewer service. We have experienced problems with our sanitary sewer service (address	
. WATERMAIN	
We have not experienced any problems with our water service. We have experienced problems with our water service (address	



PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

Do you feel the pavement surface has deteriorated to the point it needs to be fixed? Please circle one: YES NO
2. STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION
XI have observed street ponding after a significant rain. It is located at:
corner of North Ave. or Cty, 23 - NE corner
I have observed areas of erosion along the boulevard at:
Does your home or business have a sump pump? (address).
If yes, would you be interested in a sump line extended beyond the curb to hook your sump pump discharge to? Yes orNoNoNoNo
3. SANITARY SEWER
We have not experienced any problems with our sanitary sewer serviceWe have experienced problems with our sanitary sewer service (address).
4. WATERMAIN
We have not experienced any problems with our water service We have experienced problems with our water service (address).

5.	SIDEWALKS AND TRAILS (WALKING AND BIKING)
Are th	ere sidewalks or trails that you believe are missing that need to be added to the project
	es or X No
	please provide location
11 100	ploade provide location
when the whole	offer any additional information you would like to be considered as a part of these improvements: re against ability trail on North Art. This is a quiet street at least east of Cannon Valley First, with etg converns, leaple often choose to walk on the street rather than the side walk, and seem fine of an this street. Iding a bile trail appears to be a poor decision for many ocasions: I) the cost to tax payers there is no need for a trail, 2) the street has made actiful trees lining both sides. I would likely be lost if atrail was built. 3) many properties would have decaping destroyed. 4) Curb to gutter, some new as of 2019, would need to be laced. 5) streetlights would need to be moved. I more acceptable option to a bike trail would be a bike lane. The existing street although that is not really needed either. Option would be much more fiscally responsible with. Opayer monies.
	Finally, it is of note that the platting document filed in cember of 1993 by Steven Schmidt Construction for the Poairie Ils Addition specifically states that the 10 ft. easements, which includes those along North Ave., are "for drainage and utility imposes only" Not for a bike trail!
	Please do not move for ward with this Frivalous and wonted plan for a bike trail of along North Ave.
	Also with our climate, a bike trail would only be used 5-6 month. If the year. The city has not kept bile /walling trails clear of ice of



N+1a.

PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

1,	ROADWAY PAVEMENT CONDITION a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed?	
	Please circle one: YES NO	
2.	STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION	11
	I have observed street ponding after a significant rain. It is located at:	1eans
Le	orner of Woodland MAIL & Green Caf Count. For	
_	STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION I have observed street ponding after a significant rain. It is located at: Owner of Woodbard Trunil & Green On F Count. For I have observed areas of erosion along the boulevard at:	
Does	es your home or business have a sump pump? (address).	
	Yes or No	
	es, would you be interested in a sump line extended beyond the curb to hook your sump pump discharge to?	
=	Yes or MANO	
3.	SANITARY SEWER	
7	We have not experienced any problems with our sanitary sewer service. We have experienced problems with our sanitary sewer service (address	_).
4.	WATERMAIN	
>	We have not experienced any problems with our water service. We have experienced problems with our water service (address).	

Are there sidewalks or trails that you believe are missing that need to be added to the project We are $X = X = X = X = X = X = X = X = X = X $
_Yes or _XNO ABSOLUTELY NOWE
If Yes, please provide location
Dwhy A TRAIL ON North Ave? There's Afrendy
A Sidewalkow the South Side that is Rarely
Used
2 who is Alonist? Who's the stillsted with
who is paying for hingher?
3) Who is DAying for cost- SO FAR?
Thee removal
2 For [Tree Replacement)
Please offer any additional information you would like to be considered as a part of these improvements: (Lean Cutting 12 Freat Gack From Curb 15 Whenly INS Are And No Sensical. No need to Heather remode frees for construction



PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed? Please circle one: YES NO
2. STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION
X_I have observed street ponding after a significant rain. It is located at:
Corner Greenland Court + woodland trail west
have observed areas of erosion along the boulevard at:
Does your home or business have a sump pump? (address
Yes orXNo
If yes, would you be interested in a sump line extended beyond the curb to hook your sump pump discharge to?
Yes orNo
3. SANITARY SEWER
We have not experienced any problems with our sanitary sewer service. We have experienced problems with our sanitary sewer service (address).
we have it serviced occassionaly - No Backups into house
4. WATERMAIN
We have not experienced any problems with our water service. We have experienced problems with our water service (address).

5. SIDEW	ALKS AND TRAIL	-5 (WALKING AI	ib bittito)			
Are there sidewa	alks or trails that yo	ou believe are mi	issing that need	to be added to the	project	
Yes or _	X No					
Yes, please pr	ovide location					
	AL COMMENTS /		co to be consider			
			ke to be conside	red as a part of the	ese improvements:	
			ke to be conside	red as a part of the	ese improvements:	
			ke to be conside	red as a part of the	ese improvements:	
			ke to be conside	red as a part of the	ese improvements:	
			ke to be conside	red as a part of the	ese improvements:	
			ke to be conside	red as a part of the	ese improvements:	
			ke to be conside	red as a part of the	ese improvements:	
			ke to be conside	red as a part of the	ese improvements:	
			ke to be conside	red as a part of the	ese improvements:	
			ke to be conside	red as a part of the	ese improvements:	
			ke to be conside	red as a part of the	ese improvements:	
			ke to be conside	red as a part of the	ese improvements:	
			ke to be conside	ered as a part of the	ese improvements:	
			ke to be conside	ered as a part of the	ese improvements:	
			ke to be conside	red as a part of the	ese improvements:	



PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

Do you feel the pavement surface has deteriorated to the point it needs to be fixed Please circle one: YES NO	?
2. STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION	
I have observed street ponding after a significant rain. It is located at:	
I have observed areas of erosion along the boulevard at:	
Does your home or business have a sump pump? (address).
If yes, would you be interested in a sump line extended beyond the curb to hook your sump pure. Yes or No	np discharge to?
3. SANITARY SEWER We have not experienced any problems with our sanitary sewer service. We have experienced problems with our sanitary sewer service (address	1
4. WATERMAIN	,,
We have not experienced any problems with our water service. We have experienced problems with our water service (address),

5. SIDEWALKS AND TRAILS (WALKING AND BIKING)
Are there sidewalks or trails that you believe are missing that need to be added to the project Yes orNo
If Yes, please provide location
ii Tes, piease provide location
6. GENERAL COMMENTS / QUESTIONS
Please offer any additional information you would like to be considered as a part of these improvements:
Hoding the trail on the Wath side of work A
is completely unecessary, as there is a sidewalk
on the other side of the Street. There is not
encish that traffic on party the to
warrant a trait addition- Firmermore, cutting
down the trees on worm Are - both on
the south and north sides of the road is
mucessay, wespensible, and will detruct from
this neighborhood. Simply put, adding the trait
along North Ave is unnecessary and wastered of
both resurces and time.



1.

PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed? Please circle one: YES NO
2. STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION
have observed street ponding after a significant rain. It is located at:
is with hit of sanding at Greenleaf, Woodland intersection (but not bod)
I have observed areas of erosion along the boulevard at:
Does your home or business have a sump pump? (address).
Yes orNo
If yes, would you be interested in a sump line extended beyond the curb to hook your sump pump discharge to?
3. SANITARY SEWER
We have not experienced any problems with our sanitary sewer service. We have experienced problems with our sanitary sewer service (address).
4. WATERMAIN
We have not experienced any problems with our water serviceWe have experienced problems with our water service (address

Are there sidewalks or trails that you believe are missing that need to be added to the project	1.5
Yes orNo	
If Yes, please provide location	
Please offer any additional information you would like to be considered as a part of these improvem	ents:

w



2022 NW Area Mill and Overlay Project Northfield, Minnesota

1.	ROADWAY PAVEMENT CONDITION a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed? Please circle one: YES NO
2.	STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION
	_I have observed street ponding after a significant rain. It is located at:
	none.
_	_l have observed areas of erosion along the boulevard at:
_	nonl
Does	your home or business have a sump pump? (address
X	Yes orNo
	, would you be interested in a sump line extended beyond the curb to hook your sump pump discharge to? Yes or X No
3.	SANITARY SEWER
X	We have not experienced any problems with our sanitary sewer service. We have experienced problems with our sanitary sewer service (address)
4.	WATERMAIN
X	We have not experienced any problems with our water service. We have experienced problems with our water service (address
	Sib. I don't shill this is related to anyth
	Mill this of with
	related to be a lac.

Are there sid	lewalks or trails th	RAILS (WALKING A		be added to the	project	
Yes or	No previde location					
	any additional info	TS / QUESTIONS ormation you would li	1.	0/ //	se improvements:	
	Why	breaking	ereshe the	Wango	Woods	Coucheins
	Trees	should	only 6	e remire	of if oh	seased
					je.	



2022 NW Area Mill and Overlay Project Northfield, Minnesota

1.	a. Do you feel the pavement surface has deteriorated to the point it needs to be fix Please circle one: YES NO	ed?
2.	STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION	
=	_l have observed street ponding after a significant rain. It is located at:	
	I have observed areas of erosion along the boulevard at:	
	s your home or business have a sump pump? (address	<u>)</u> ,
	s, would you be interested in a sump line extended beyond the curb to hook your sump p	ump discharge to?
X	Yes or No	
3.	SANITARY SEWER	
×	We have not experienced any problems with our sanitary sewer service. We have experienced problems with our sanitary sewer service (address	
4.	WATERMAIN	
X)

Are t	SIDEWALKS AND TRAILS (WALKING AND BIKING)
	nere sidewalks or trails that you believe are missing that need to be added to the project
	Yes or No
If Yes	, please provide location
-	
Pleas	e offer any additional information you would like to be considered as a part of these improvements:
	and any distribution in the first result like to be considered do a part of those improvements.
	a survey assured an intermediate in your module line to be continuously as a part of those improvements.
_	a same and a
	a salitation in the mattern you mean mile to be considered as a part of those improvements.
	The state of the s



2022 NW Area Mill and Overlay Project Northfield, Minnesota

1.	ROADWAY PAVEMENT CONDITION					
	a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed?					
	Please circle one: YES (NO)					
2.	STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION					
X	I have observed street ponding after a significant rain. It is located at:					
	Veodland Tr1 + Oriential Ct.					
_						
-	I have observed areas of erosion along the boulevard at:					
Does	your home or business have a sump pump? (address_					
XX	es orNo					
	would you be interested in a sump line extended beyond the curb to hook your sump pump discharge to?					
	그런 마이트 그런 그는 사람이 많아 보이면 하는 것이 되었다. 그 사람이 되어 있다고 있다는 그렇게 되어 있다면 하는데 하는데 이렇게 되었다면 하다 하는데 하다 하는데 없다.					
Y	es or No					
3.	SANITARY SEWER					
X	We have not experienced any problems with our sanitary sewer service.					
	We have experienced problems with our sanitary sewer service (address).					
4.	WATERMAIN					
X	We have not experienced any problems with our water service.					
	We have experienced problems with our water service (address).					

5. SIDEWALKS AND TRAILS (WALKING AND BIKING)	
Are there sidewalks or trails that you believe are missing that need to be added to the project	
Yes (or X No)	
f Yes, please provide location	
lease offer any additional information you would like to be considered as a part of these improvements: We do not need a paved buke trail along North Are. Paint will be sufficient. Paint the crosswalks. Paint abouted Plow the existing trails. We do not need a separate trail.	t



2022 NW Area Mill and Overlay Project Northfield, Minnesota

1.	ROADWAY PAVEMENT CONDITION a. Do you feel-the pavement surface has deteriorated to the point it needs to be fixed? Please circle one: YES NO
	Pavement is starting to show signs of wear, but resurfacing not needed quite yet.
2.	STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION
X	I have observed street ponding after a significant rain. It is located at:
The	intersection of Greenleaf Court and Woodland Trail
-	intersection of electrical equit and vyocalaria frain
	I have observed areas of erosion along the boulevard at:
Does	your home or business have a sump pump? (address
XY	'es or _ No
	would you be interested in a sump line extended beyond the curb to hook your sump pump discharge to?
Y	es or X No Yes, but but not to Woodland Trail. Our sump pump is in back and drains toward the rear of the prope
	res, but but not to vicodiand Trail. Our sump pump is in back and drains toward the real of the proper
3.	SANITARY SEWER
X	We have not experienced any problems with our sanitary sewer service.
	We have experienced problems with our sanitary sewer service. We have experienced problems with our sanitary sewer service (address
4.	WATERMAIN
×	
	We have not experienced any problems with our water service. We have experienced problems with our water service (address
	The state of the s

5. SIDEWALKS AND TRAILS (WALKING AND BIKING)
Are there sidewalks or trails that you believe are missing that need to be added to the project
Yes or X No
If Yes, please provide location
Woodland Trail was conceived to preserve the wooded feel of the neighborhood. Adding trails or sidewalks would require
removing lots of trees and would permanantly destroy the feel of the neighborhood. We have very little traffic and
the street is perfectly hospitible to walkers, runners, and bicyclists. Many people have told me how they love walking
through the woods and I love it myself. My wife and I walk the trail several times a day/week and rarely encounter a vehicle
to threaten our safety. I have 2 children that grew up in our house and walked to Greenvale school every day without
any worry for their safety. In fact, North Ave has a sidewalk that is rarely completely cleared of snow in the winter. That is far more problematic than walking in the street on Woodland Trl where there is very little traffic.
6. GENERAL COMMENTS / QUESTIONS Please offer any additional information you would like to be considered as a part of these improvements: I am VERY concerned about whatever bike trail you are considering on North Ave. From your map and from the master
map from Toole Design Group on the City of Northfield's website, as well as the tagging of all the trees, it appears the city
is going to remove all the trees along the north side of North Ave. to put in a bike path. If this is true, this is insanity. Are we trying to reduce our carbon footprint by removing dozens of mature trees along North Ave and by putting down
an impervious bituminous surface that absorbs and emanates heat?!? Not to mention the carbon cost of producing the
bituminous itself or the enormous actual cost of removing the trees and laying down the bitiminous.
I would suggest removing the parking on North Ave and installing bike lanes along the sides of North Ave as a better
solution. From my observation over 22 years, I have rarely seen bikers on any of the trails on this side of town. They are
mainly used by walkers and joggers. Bikers generally use the roadway. I am a biker myself and I never use the city trails
because I ride too quickly to deal with the crossings and twists and turns on the city bike path. Protected lanes on the street are
are very hospitible to bikers. Furthermore, the biggest growth in the bicycle market are electric assist bikes, which are
much too fast for a city bike trail.
If you insist on a separate bike trail, an alternate solution would be to tear out the sidewalk on the south side of the North Ave so you don't have to destroy all the trees on the north side. I think this is a waste as well as you can legally ride on the sidewalk and it will last longer, but it's an option.
If a sell that the sell and the sell at th
If you still insist on a trail on the north side of North Ave, you need to strongly consider drainage. The south end of the woods floods often. If you put in a trail, you need to make sure that area drains or the water will potentially seep
underground back toward the houses and our basements. Additionally, the water will ruin your new trail. Also, the trees
and grass are rarely ever trimmed on that stretch of North Ave. You'd have to make a commitment to trimming and mowing on a far mo regular basis or the trail will be unusable. I am skeptical you will commit to this because you don't do it now.
Togard. Such S. 1.10 than win so distribute. I aim shopfied you win commit to this booduse you don't do it now.



2022 NW Area Mill and Overlay Project Northfield, Minnesota

a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed? Please circle one: YES NO
2. STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION
— I have observed street ponding after a significant rain. It is located at: West Knd of North Street By Pondi) Across from Be I have observed areas of erosion along the boulevard at:
Does your home or business have a sump pump? (address
XYes orNo
If yes, would you be interested in a sump line extended beyond the curb to hook your sump pump discharge to? Yes orNo
3. SANITARY SEWER
We have not experienced any problems with our sanitary sewer service. We have experienced problems with our sanitary sewer service (address).
4. WATERMAIN
We have not experienced any problems with our water service. We have experienced problems with our water service (address

SIDEWALKS AND TRAILS (WALKING AND BIKING)	
. /	
es or A No	
please provide location	
bout at the Corner of Worth, Eleventh, I	s 1
hieles.	
	GENERAL COMMENTS/QUESTIONS offer any additional information you would like to be considered as a part of these improvements: This is to take place a round bout at the Corner of Morth, Fleventh,





PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed? Please circle one: YES NO
Intersection of Commen Valley Drive and North Are
2. STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION
I have observed street ponding after a significant rain. It is located at:
inferjection of B Lincoln St + Connon Yally Drove by Kildell Agris: I have observed areas of erosion along the boulevard at:
Does your home or business have a sump pump? (address). X Yes or No
If yes, would you be interested in a sump line extended beyond the curb to hook your sump pump discharge to?
Yes or K_No
3. SANITARY SEWER
We have not experienced any problems with our sanitary sewer service. We have experienced problems with our sanitary sewer service (address).
4. WATERMAIN
We have not experienced any problems with our water serviceWe have experienced problems with our water service (address).

5. SIDEWALKS AND TRAILS (WALKING AND BIKING)
Are there sidewalks or trails that you believe are missing that need to be added to the project
Yes or X No
If Yes, please provide location
But, comile a wider shoulder on Dresder Are or bike lare since a sot of people use that as a bike route
GENERAL COMMENTS / QUESTIONS Please offer any additional information you would like to be considered as a part of these improvements:



2022 NW Area Mill and Overlay Project Northfield, Minnesota

1.	ROADWAY PAVEMENT CONDITION	₩	APPLIES TO
0	Do you feel the pavement surface has deteriorated to the po Please circle one: YES NO NO NO NO NO NO NO NO NO N	oint it needs to be fixed?	APPLIES TO WEST END PARKWAY IN THYE PKW
2.	STORM SEWER, STORM WATER DRAINAGE AND SURFACE	EROSION 13/3	THYE PLW
	_I have observed street ponding after a significant rain. It is located	at:	
	_I have observed areas of erosion along the boulevard at:		
. /	s your home or business have a sump pump? (address		<u>)</u> ,
	s, would you be interested in a sump line extended beyond the curb to	o hook your sump pump c	lischarge to?
_	Yes orNo		
3.	SANITARY SEWER		
	We have not experienced any problems with our sanitary sewer ser).
4.	WATERMAIN		
V	_We have not experienced any problems with our water service. _We have experienced problems with our water service (address		

5. SIDEWAL	LKS AND TRAILS (WALKING AND BIKING)
Are there sidewalk	ss or trails that you believe are missing that need to be added to the project
$_$ Yes or X	<u>√</u> No
f Yes, please prov	ride location
4	
76475	
V 7	
lease offer any ac	dditional information you would like to be considered as a part of these improvements:
	Ubanglesis with 1821



PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed? Please circle one: YES NO	
2. STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION	
I have observed street ponding after a significant rain. It is located at:	
I have observed areas of erosion along the boulevard at:	
Does your home or business have a sump pump? (address Yes or No	_ <u>j</u> ,
If yes, would you be interested in a sump line extended beyond the curb to hook your sump pump dischage. Yes or X No	arge to?
3. SANITARY SEWER	
We have not experienced any problems with our sanitary sewer serviceWe have experienced problems with our sanitary sewer service (address).
4. WATERMAIN	
We have not experienced any problems with our water serviceWe have experienced problems with our water service (address	_),

5.	SIDEWALKS AND TRAILS (WALKING AND BIKING)
Are th	ere sidewalks or trails that you believe are missing that need to be added to the project
Y	es orNo
If Yes,	please provide location
20.14	offer any additional information you would like to be considered as a part of these improvements:



1.

PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

 a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed? Please circle one: YES NO 				
2. STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION				
I have observed street ponding after a significant rain. It is located at:				
1404 Cannon Valley Dr.				
I have observed areas of erosion along the boulevard at:				
Does your home or business have a sump pump? (address). Yes or No				
If yes, would you be interested in a sump line extended beyond the curb to hook your sump pump discharge to? Yes orNo				
3. SANITARY SEWER				
We have not experienced any problems with our sanitary sewer serviceWe have experienced problems with our sanitary sewer service (address)_				
4. WATERMAIN				
We have not experienced any problems with our water serviceWe have experienced problems with our water service (address).				

5.	SIDEWALKS AND TRAILS (WALKING AND BIKING)
re th	ere sidewalks or trails that you believe are missing that need to be added to the project
,	es or V No
	please provide location
1 100	please provide location
_	
lease	GENERAL COMMENTS / QUESTIONS offer any additional information you would like to be considered as a part of these improvements:
lease	offer any additional information you would like to be considered as a part of these improvements: Thouse at is at the point where Liberty Park sing development starts. As a result, the surfaces of that area the road south meet as been the mid-point of our driveway:
lease how an	offer any additional information you would like to be considered as a part of these improvements: (house at
lease how an	offer any additional information vou would like to be considered as a part of these improvements: (house at the point where liberty Park to at the point where liberty Park to at the point where liberty Park to a result, the surfaces of that area the road south meet at the mid-point of our driveway: (other words we hope you can extend the new surface peyord our we way entrance:
lease hou an	offer any additional information you would like to be considered as a part of these improvements: (house at
lease hou an	offer any additional information vou would like to be considered as a part of these improvements: (house at the point where liberty Park to at the point where liberty Park to at the point where liberty Park to a result, the surfaces of that area the road south meet at the mid-point of our driveway: (other words we hope you can extend the new surface peyord our we way entrance:
lease Di hoi an In	offer any additional information vou would like to be considered as a part of these improvements: (house at the point where liberty Park to at the point where liberty Park to at the point where liberty Park to a result, the surfaces of that area the road south meet at the mid-point of our driveway: (other words we hope you can extend the new surface peyord our we way entrance:
lease Di hoi an In	offer any additional information vou would like to be considered as a part of these improvements: (house at the point where liberty Park to at the point where liberty Park to at the point where liberty Park to a result, the surfaces of that area the road south meet at the mid-point of our driveway: (other words we hope you can extend the new surface peyord our we way entrance:
lease hou an	offer any additional information vou would like to be considered as a part of these improvements: (house at the point where liberty Park to at the point where liberty Park to at the point where liberty Park to a result, the surfaces of that area the road south meet at the mid-point of our driveway: (other words we hope you can extend the new surface peyord our we way entrance:
lease hoi an	offer any additional information vou would like to be considered as a part of these improvements: (house at the point where liberty Park to at the point where liberty Park to at the point where liberty Park to a result, the surfaces of that area the road south meet at the mid-point of our driveway: (other words we hope you can extend the new surface peyord our we way entrance:
Please Cu hoi an In	offer any additional information vou would like to be considered as a part of these improvements: (house at the point where liberty Park to at the point where liberty Park to at the point where liberty Park to a result, the surfaces of that area the road south meet at the mid-point of our driveway: (other words we hope you can extend the new surface peyord our we way entrance:
hoi an In	offer any additional information vou would like to be considered as a part of these improvements: (house at the point where liberty Park to at the point where liberty Park to at the point where liberty Park to a result, the surfaces of that area the road south meet at the mid-point of our driveway: (other words we hope you can extend the new surface peyord our we way entrance:
Please Cu hoi an In	offer any additional information vou would like to be considered as a part of these improvements: (house at the point where liberty Park to at the point where liberty Park to at the point where liberty Park to a result, the surfaces of that area the road south meet at the mid-point of our driveway: (other words we hope you can extend the new surface peyord our we way entrance:
Please Cu hoi an In	offer any additional information vou would like to be considered as a part of these improvements: (house at the point where liberty Park to at the point where liberty Park to at the point where liberty Park to a result, the surfaces of that area the road south meet at the mid-point of our driveway: (other words we hope you can extend the new surface peyord our we way entrance:



1.

PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

a. Do you feel the pavement surface has deteriorated to the point it need Please circle one: YES NO - LUPIN	ds to be fixed? OF DRIVE
2. STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSIO	N
No I have observed street ponding after a significant rain. It is located at:	
NONE	
No I have observed areas of erosion along the boulevard at: No N∈	
Does your home or business have a sump pump? (address_	<u>)</u> .
X_Yes orNo	
If yes, would you be interested in a sump line extended beyond the curb to hook you	ur sump pump discharge to?
Yes orX_No	
3. SANITARY SEWER	
We have not experienced any problems with our sanitary sewer service. We have experienced problems with our sanitary sewer service (address	
4. WATERMAIN	
We have not experienced any problems with our water serviceWe have experienced problems with our water service (address).

5. SIDEWALKS AND TRAILS (WALKING AND BIKING)	
Are there sidewalks or trails that you believe are missing that need to be added to the project	
Yes or X No	
If Yes, please provide location	
Please offer any additional information you would like to be considered as a part of these improvements: PLEASE CONSIDER RESURFACING BLUE FLAGET AND PHOX CT WHEN LUPINE DRIS RESURFACED, CITY AND STORM SEWER LINES RUN WOEK THE TWO STREET WOULD REQUIRE REPAIR MY UNDERSTANDING IS CIT RESPONSIBLE FOR REPAIR THE BROKEN LINE AND REPA	BLUE WATER SEWER TAND IF ALINE



PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

	Do you feel the pavement surface has deteriorated to the point it needs to be fixed? Please circle one: YES NO NO NO NO NO NO NO NO NO N	
2.	STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION	
_	I have observed street ponding after a significant rain. It is located at:	
_	I have observed areas of erosion along the boulevard at:	
. /	your home or business have a sump pump? (address). Yes or No	
If yes,	would you be interested in a sump line extended beyond the curb to hook your sump pump discharge to? Yes or Who if all no cost	
3.	SANITARY SEWER We have not experienced any problems with our sanitary sewer service. We have experienced problems with our sanitary sewer service (address	j.
4. —V	WATERMAIN We have not experienced any problems with our water service. We have experienced problems with our water service (address	

SIDEWA	LKS AND TRAILS (WALKING AND BIKING)
e there sidewal	ks or trails that you believe are missing that need to be added to the project
_Yes or _	
Yes, please pro	vide location
	Oh-Sweet hileway as a part of these improvements:
	Lichwood Dr & thre Parkwey do not yeed to be fixed at this time frere are no pot holes as or
	alimaced areas
	O Company of the comp



Please circle one:

1.

PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

The City values input from residents who live along the project corridor as you have first-hand knowledge of how the streets and utilities function. Your comments / concerns will assist us during the preliminary design and layout of the project. We encourage you to take a few minutes to fill out the following questionnaire. Completed questionnaires can be collected at the Neighborhood Meeting, emailed to Sean.Simonson@ci.northfield.mn.us or dropped off at the Engineering Office located at Northfield City Hall, 801 Washington Street.

a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed?

STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION	
have observed street ponding after a significant rain. It is located at:	<u></u>
CORNER OF QUIE + ROLVAAG CT, IN FRONT of DRIVEWAY ANDAISO Alo	Ny propenty 100
have observed areas of erosion along the boulevard at:	
IN ROUND area of Rolvang C+ North END + IN Places along Go	DLE NEAR
Does your home or business have a sump pump? (address).	
X Yes or No	
If yes, would you be interested in a sump line extended beyond the curb to hook your sump pump discharge to?	
Yes or X No Do Not Need	
3. SANITARY SEWER	
We have not experienced any problems with our sanitary sewer service. We have experienced problems with our sanitary sewer service (address	ov, h dean
4. WATERMAIN	
We have not experienced any problems with our water service. We have experienced problems with our water service (address	

5.	SIDEWAL	KS AND TR	AILS (WALKING	AND BIKING)				
Are	there sidewalk	s or trails tha	it you believe are	e missing that need to be	e added to the p	roiect		
	_Yes or 🗶							
II Y	es, please provi	ide location						
-								
_								
-								
_								
_								
-								
Plea				d like to be considered				
+	QUIE	Think		Necessary MAYBE	to put	bike	MARK	1195
B	IKE LAN	ES on	the sides	MAPBE	on Thye	PRWY	BUT	How ABOOT
_				•				
_								
_								
	.1.							



1.

PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

	a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed? Please circle one: NO NO
2.	STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION
X	STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION I have observed street ponding after a significant rain. It is located at: Netyhkar Herse
	have observed areas of erosion along the boulevard at:
	No
4.4	your home or business have a sump pump? (address).
	es orNo
- 2	would you be interested in a sump line extended beyond the curb to hook your sump pump discharge to? Yes orNoNoNoNoNoNoNoNO
3.	SANITARY SEWER
×	We have not experienced any problems with our sanitary sewer service. We have experienced problems with our sanitary sewer service (address).
4.	WATERMAIN
	We have not experienced any problems with our water service. We have experienced problems with our water service (address).

ra thara aidamalle auto	AND TRAILS (WALKING AND BIKING)				
e there sidewalks or ti	rails that you believe are missing that need to be added to the project				
Yes or X No					
Yes, please provide lo	cation				
	nal information you would like to be considered as a part of these improvements:				



2022 NW Area Mill and Overlay Project Northfield, Minnesota

ROADWAY PAVEMENT CONDITION a. Do you feel the pavement surface has deteriorated to the point it needs Please circle one: NO	s to be fixed?
2. STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION	
I have observed street ponding after a significant rain. It is located at:	
1 have observed areas of erosion along the boulevard at:	
Does your home or business have a sump pump? (address	
Yes orNo	
If yes, would you be interested in a sump line extended beyond the curb to hook your	sump pump discharge to?
Yes orNo	the rate of the party of the pa
3. SANITARY SEWER	
We have not experienced any problems with our sanitary sewer serviceWe have experienced problems with our sanitary sewer service (address).
4. WATERMAIN	A
We have not experienced any problems with our water service. CC>SSION We have experienced problems with our water service (address	ally-during summer); Exalt: 40-9001 (home-outside fauce+)


Are there sidewalks or trails that you believe are missing that need to be added to the project	
Yes or No	
If Yes, please provide location	
+ see comments 6.1.1, 6.1.2, 6.1.3 6.1.4 below in section 6	_
regarding the addition of a forth trail connection to the	-
_ LI VCO / I SHE IMAGE	_
	_
	-
I. I there are currently three entry/exit paths to the Liberty And trail - more than a lacated on the south side of the pond! trail to connect with Wood land Trail which surrounds the ablic George Rysgaard Nath Preserve. A public right a way currently exists between the Rod wolland will and the is an existing from the liberty form that the new is an existing from the liberty form that the new form of the new fourth trail connection is not needed and that its allocated fundscally be better spent on higher priority trail restoration and maintenant does not end up existing into a residential area.	PRATA dent
	_
	-
	-
	-
	-



2022 NW Area Mill and Overlay Project Northfield, Minnesota

1.	ROADWAY PAVEMENT CONDIT a. Do you feel the pavement sur		proted to the point i	t poods to be fived?	
	 a. Do you feel the pavement sur Please circle one: 	YES	NO NO	r needs to be lixed?	
2.	STORM SEWER, STORM WATER	R DRAINAGE /	AND SURFACE ER	OSION	
No	_I have observed street ponding after	a significant ra	in. It is located at:		
NO	I have observed areas of erosion alor	ng the bouleva	rd at:		
/	your home or business have a sump p Yes or No	oump? (addres	s_).
	res or No , would you be interested in a sump lin	e extended be	vond the curb to ho	ok vour sump pump di	scharge to?
	Yes or V No		,	, , , , , , , , , , , , , , , , , , , ,	
3.	SANITARY SEWER				
	_We have not experienced any probler _We have experienced problems with o).
4.	WATERMAIN				
	We have not experienced any problem We have experienced problems with o).

5. SIDEWA	ALKS AND TRAILS (V	VALKING AND BIKING)			
Are there sidewal	lks or trails that you b	elieve are missing that need	I to be added to the project	t.	
Yes or	No ovide location h there co Wood land		walking the walking Drive		nd the rul make t perhaps
we also	11101111111	V T	possibility th	osed was	troos mig
		you would like to be considently missing this missing the consideration with the considerat	ered as a part of these important for the poversay preject		soliciting





2022 NW Area Mill and Overlay Project Northfield, Minnesota

1. ROADWAY PAVEMENT CONDITION a. Do you feel the pavement surface has deteriorated to the point it need Please circle one: YES NO THE SUR	
C) THESLE	FACE ON THYME PARKUAY IS
3 STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSIO	A die in the line in the line
have observed street ponding after a significant rain. It is located at:	AT THE JUNCTURE
	PROAD DAMAGE IS
have observed areas of erosion along the boulevard at:	EXACERBATE BY CIM
	USE OF DO CAR WITH
	WING BLADES THAT DO
Does your home or business have a sump pump? (address). NOT PROPERTY
Yes orNo	FLUAT DURING SNOW
	REMOVAL
If yes, would you be interested in a sump line extended beyond the curb to hook yo	Fruncise of Man
Yes orNo	FELS WHEN ONFOR
	STREETS - LIKE AROUND
3. SANITARY SEWER	BRIDGE SQUARE
We have not experienced any problems with our sanitary sewer service.	SHOWS HAVE
We have experienced problems with our sanitary sewer service (address	Amanon.
4. WATERMAIN	ONLY ARIA THAT NEEDS WORK IS LOCKWOOD DRIVE
We have not experienced any problems with our water service.	
We have experienced problems with our water service (address	MORTH TO INTERSECTION OF
	THYNG PARKUMY
& City Stroug Fusing Timery Comp	- LITION By CONTESTIVE
LAT WORK ON LOCKWOOD DRIVE EXT	ENDED TILL LOVEMBER
(4+ Monnes OF LITTLE WORK)	

Are there sidewalks or trails that you believe are missing that need to be added to the project
No
If Yes, please provide location RESLIZITEDING TRALS FROUND LIBERTY PARK RETURNON PONDS WOULD BE HELPFUL THE SEALING OF COPERS IN TRAIS RECENTY 2021 TUNE DID ABSOLUTELY RETURNS TO THAT PICOBLEM, AND STILL LEFT MAJOR GAPS IN SURFACE OF THE SURFACE O
WALK TO INSPECT WORK
6. GENERAL COMMENTS / QUESTIONS Please offer any additional information you would like to be considered as a part of these improvements: Output Deeds Propure Equipment To Course Snow From
MAK WAYS AND PATHS. USE OF PLEWS ON CITY PLOKED TRUKES AND LARGOR CATS NOT APPROPRIATE. THESE PLOW BLADES ARE
6 For Pers in WIDH, LARGER THAN PATHWAYS AND THEREFORE
AND ALLE LURANES EXOSION. THE SMALLER PLOWS THAT ARE USED DOWNTOWN PROBABLY MIRE APPROPRIATE
=> CONSTRUCTION HOURS NOT RESULT IN LOSS OF TREES" ON PARKUM
EFFER MILL EVER HAY ARTHURS

5.

SIDEWALKS AND TRAILS (WALKING AND BIKING)



2022 NW Area Mill and Overlay Project Northfield, Minnesota

I. ROADWAT PAVEMENT CONDITI			-
a. Do you feel the pavement sur Please circle one:	YES deterior	ated to the point it needs to be fixe NO	d?
2. STORM SEWER, STORM WATER	R DRAINAGE AN	D SURFACE EROSION	
I have observed street ponding after	a significant rain.	It is located at:	
Thre Packing + Que UN	1 Thre	+ Loc/Cuent	
have observed areas of erosion alor	ng the boulevard	at:	
Does your home or business have a sump	oump? (address_).
XYes orNo			
If yes, would you be interested in a sump lir	ne extended beyo	and the curb to hook your sump pu	mp discharge to?
XYes orNo			
3. SANITARY SEWER			
We have not experienced any proble We have experienced problems with).
4. WATERMAIN			
X We have not experienced any proble We have experienced problems with).

5.	SIDEWALKS AND TRAILS (WALKING AND BIKING)
Are th	ere sidewalks or trails that you believe are missing that need to be added to the project
	es or No
f Yes	please provide location
	GENERAL COMMENTS / QUESTIONS coffer any additional information you would like to be considered as a part of these improvements:
Pleas	offer any additional information you would like to be considered as a part of these improvements:
Pleas	
Pleas	offer any additional information you would like to be considered as a part of these improvements:
Pleas	offer any additional information you would like to be considered as a part of these improvements:
Pleas	offer any additional information you would like to be considered as a part of these improvements:
leas	offer any additional information you would like to be considered as a part of these improvements:
Pleas	offer any additional information you would like to be considered as a part of these improvements:
leas	offer any additional information you would like to be considered as a part of these improvements:
Pleas	offer any additional information you would like to be considered as a part of these improvements:
leas	offer any additional information you would like to be considered as a part of these improvements:
Pleas	offer any additional information you would like to be considered as a part of these improvements:
Pleas	offer any additional information you would like to be considered as a part of these improvements:
Pleas	offer any additional information you would like to be considered as a part of these improvements:
Pleas	offer any additional information you would like to be considered as a part of these improvements:
Pleas	offer any additional information you would like to be considered as a part of these improvements:
Pleas	offer any additional information you would like to be considered as a part of these improvements:
7	offer any additional information you would like to be considered as a part of these improvements:



1.

PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

 Do you feel the pavement surface has deteriorated to the point it needs to be fixed? Please circle one: YES NO 	
2. STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION	
I have observed street ponding after a significant rain. It is located at:	
I have observed areas of erosion along the boulevard at:	
Does your home or business have a sump pump? (address	
If yes, would you be interested in a sump line extended beyond the curb to hook your sump pump discharged a sump line extended beyond the curb to hook your sump pump discharged a sump line extended beyond the curb to hook your sump pump discharged a sump line extended beyond the curb to hook your sump pump discharged a sump line extended beyond the curb to hook your sump pump discharged a sump line extended beyond the curb to hook your sump pump discharged a sump line extended beyond the curb to hook your sump pump discharged a sump line extended beyond the curb to hook your sump pump discharged a sump line extended beyond the curb to hook your sump pump discharged a sump line extended beyond the curb to hook your sump pump discharged a sump line extended beyond the curb to hook your sump pump discharged a sump line extended beyond the curb to hook your sump pump discharged a sump line extended beyond the curb to hook your sump pump line extended beyond the sum of	ge to?
3. SANITARY SEWER We have not experienced any problems with our sanitary sewer service. We have experienced problems with our sanitary sewer service.	
We have experienced problems with our sanitary sewer service (address).
We have not experienced any problems with our water service. We have experienced problems with our water service (address).	

Are there sidewa	alks or trails th	hat vou believe	e are missing th	nat need to be	added to the p	roject		
Yes or _			are misering a	iat mood to bo	daded to the pi	roject		
BE E INCO CONCER REMA	RE WILL EXDEN AS WE AS WE W. P	PLE V	HOUSE TO DO NITH S NATER ENANC NOW!	S. THE IT CO HALLO RUN O E IS A	RE IS RRECTI W ROO OFF IN CONCE	A SU	BEHIND DOE A HAVE I WOULD Y Y AVE REPAIR T MAIN LY CU	1XI) WOUL A D COT D 15 A S, SUDW
. GENERA	AL COMMEN	ITS / QUESTIO	ONS					
Please offer any a	additional info	ormation you w	ould like to be	considered as	a part of these	e improvemen	ts:	
		To the second		1 0				
								179

SIDEWALKS AND TRAILS (WALKING AND BIKING)

5.




2022 NW Area Mill and Overlay Project Northfield, Minnesota

ROADWAY PAVEMENT CONDITION a. Do you feel the pavement surface has deteriorated to the point it needs to	. 10
Please circle one: YES NO Not Sure Thye Rkwy From C	Quie La replacement
2. STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION	Jule 24 Ween's Peptacemen
I have observed street ponding after a significant rain. It is located at:	
North Quie LN and Patriot Rd intersacti	on
I have observed areas of erosion along the boulevard at:	
Does your home or business have a sump pump? (address).
Yes or No	
If yes, would you be interested in a sump line extended beyond the curb to hook your se	ump pump discharge to?
X Yes or No Depends on cost	
3. SANITARY SEWER	
We have not experienced any problems with our sanitary sewer service. We have experienced problems with our sanitary sewer service (address).
4. WATERMAIN	
We have not experienced any problems with our water service. We have experienced problems with our water service (address	Ď,

. SIDEW	ALKS AND	RAILS (WALK	and biking	1				
re there sidewa	alks or trails	hat you believe	e are missing that	need to be adde	ed to the proje	ct		
Yes or _					e in the proje			
Yes, please pr								
5	ee att	tached .	sheet					
		NTS / QUESTIO	ONS ould like to be con	nsidered as a pa	rt of these imp	provements:		
ase offer any a	additional info	ormation you w					as	
ease offer any a	ecra+ e	ormation you w	vould like to be con	walkin		biking	a s	
ase offer any a	ecra+ e	ormation you w	vould like to be con	walkin	g and	biking	u s	
ase offer any a	ecra+ e	ormation you w	vould like to be con	walkin	g and	biking	ii §	
ase offer any a	ecra+ e	ormation you w	vould like to be con	walkin	g and	biking	ii \$	
ase offer any a	ecra+ e	ormation you w	vould like to be con	walkin	g and	biking	ii §	
ase offer any a	ecra+ e	ormation you w	vould like to be con	walkin	g and	biking	a s	
ase offer any a	ecra+ e	ormation you w	vould like to be con	walkin	g and	biking	a s	
ease offer any a	ecra+ e	ormation you w	vould like to be con	walkin	g and	biking	us	
ease offer any a	ecra+ e	ormation you w	vould like to be con	walkin	g and	biking	us	
ease offer any a	ecra+ e	ormation you w	vould like to be con	walkin	g and	biking	as	
ease offer any a	ecra+ e	ormation you w	vould like to be con	walkin	g and	biking	a s	
ease offer any a	ecra+ e	ormation you w	vould like to be con	walkin	g and	biking	a S	
ease offer any a	ecra+ e	ormation you w	vould like to be con	walkin	g and	biking	a s	

Proposed 2022 NW Area Mill and Overlay Project Input



Bike & Walking Trail and Sidewalk

Intersection Cedar & Thye Parkway

Provide connection for walking and biking from north to south sidewalk and trail pathway

Pathway along Cedar from Thye Parkway to North Ave Plant material coming up and holes

Pathway around pond south of Thye Parkway Plant material coming up and holes

Intersection Cedar & North Ave

NW corner connection with walking and biking trail pathway has ponding and difficult access

Way to connect biking from North Ave. & Bethel Church to Lincoln Pkwy & Linden St Intersection

Possible bike pathway to Downtown Intersection Lincoln Pkwy & Linden St to St. Olaf Ave St. Olaf Ave to Linden St South to 2nd St and then Hwy 3

Street Mill and Overlay

Intersection Thye Pkwy & Lockwood Dr south to Quie Ln Mill and overlay

Not sure Thye Pkwy from Quie Ln to Cedar needs mill and overlay

North Quie Ln & Patriot Rd intersection has ponding

North Quie Ln has breakup at sewer cover center of road plus numerous cracks across the road

July 4, 2021



PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

1. ROADWAY PAVEMENT CONDITION	
a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed? Please circle one: YES > NO	
On the STREETS indicated in your Project map.	
2. STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION	
I have observed street ponding after a significant rain. It is located at:	
At Lockwood & THYE Parkway. At Greenvale at the Progressive Rail crossing	
I have observed areas of erosion along the boulevard at:	
and bodieval a di,	
Does your home or huginage have a comment of a Li	
Does your home or business have a sump pump? (address).	
XYes orNo	
If yes, would you be interested in a sump line extended beyond the curb to hook your sump pump discharge to?	1
_ Yes or X No We are discharging the water to the back of our proper	to.
Ties of And the me discussion of the	1
3. SANITARY SEWER	
V w	
We have not experienced any problems with our sanitary sewer service.	
We have experienced problems with our sanitary sewer service (address).	
4. WATERMAIN	
No. 200 and a second se	
We have not experienced any problems with our water service.	
We have experienced problems with our water service (address	
Pare 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1
Occasionally we get brown water from our faucets. It is probably coming from the City's hydrent flushing	<i>T</i>
is probable Coming from the City's higher & Shicking	
John January Justing	
ophitions.	

icie sidewaiks of	trails that you bel	lieve are missing that i	need to be added to	the project	
Yes or No	0				
s, please provide	location				j
There a	re some	broken	Sidewal	1 sections and	
deprisses	1 sidew	alk length	s on the	south side of Nor	th
Avenue.		0			
FIV WILL,					
					-
ase offer any additi	onal information y	you would like to be co	nsidered as a part of		
See	my left	a dated	July 4,	2021	
	J				
		M63 31 2			

5.

SIDEWALKS AND TRAILS (WALKING AND BIKING)

Northfield, MN 55057 July 4, 2021

Sean Simonson
Engineering Manager
Engineering Department
City of Northfield
City Hall
801 Washington Street
Northfield, Minnesota 55057

Subject: Return of Completed Project Questionnaire for 2022 NW Area Mill and Overlay Project

Dear Mr. Simonson:

I am the Property Owner at the address first shown above. I am returning the subject Questionnaire that you mailed to me on July 2, 2021. I have completed the Questionnaire with the help of my spouse, We will be out-of-town at the time of your public meeting on July 14, 2021; consequently, I am using this letter to convey our comments on the City's proposed project.

- Overall, I am in general support of all parts of the mill and overlay project planned for the NW corner of the City.
- 2. With respect to the proposed, on-street bikeway to be created on the existing, south side of Thye Parkway, it is my suggestion that you should find some way to provide signage for auto drivers at both ends of the new bikeway. The signage should make clear where autos are to be operating in the revised street profile. We have had difficulty in figuring out where you want autos to travel when we suddenly come upon the pieces of bikeway that are appearing on existing City streets on the south side of the Wells Fargo property, for example. The problem mainly stems from the absence of a painted center line for the two-way auto lanes.
- I hope you will pay special attention to re-doing the storm water drainage where Lockwood Drive first intersects Thye Parkway on the south side of the Parkway. Storm and snow melt water tend to collect across the width of

Lockwood Drive at the meeting of the two streets and does not drain away. In the winter, the water becomes an icy slush that makes the intersection treacherous. The water and ice, and auto traffic, punish the existing asphalt and concrete swale creating potholes that the City must frequently repair. There is something wrong with the storm water drainage at this corner.

- 4. I do not understand the purpose for the short piece of Trail proposed on the west side of the nameless park behind the homes on the north end of Cannon Valley Drive E. This large expanse of park is grossly underutilized. The park has no trees, no shelter, no picnic benches, no ball fields, no soccer nets, and few users. The City spends substantial time mowing the dandelions and grass. Could the Parks Commission do something to make better use of this prime land?
- I do not understand the purpose for the long, new Trail proposed for the north side of North Avenue. There is already an existing sidewalk on the south side of this Avenue. The sidewalk needs repairs or elevating in a few sections.
- 6. I strongly endorse your plan to add some short pieces of new sidewalk eastwest along Greenvale Avenue and north-south from Greenvale to the private driveway at the St. Dominic Parish Center/School. Many people walk along this pathway to reach Downtown Northfield from the apartment and retirement homes in this area, and to attend St. Dominic Church. I will observe that the proposed sidewalk additions end at St. Dominic's private driveway coming off Spring Street North. Pedestrians and bicyclists already use the private driveway, and the entrance road for St. Dominic School, to continue their travel from Greenvale/Spring Street to St. Olaf Avenue and thus to Downtown. This traffic occurs because (a) there is no sidewalk south of the St. Dominic Parish Center and (b) the road surface on Spring Street approaching St. Olaf Avenue is always in a state of bad repair and covered with ice and slush in winter. Does the City have an easement with St. Dominic Church providing for pedestrians and bicycle operators to make increased use of the Church's private driveways?
- 7. I make frequent use of Greenvale Avenue and the bridge over the CP tracks to reach Hwy 3 and Downtown Northfield. There is a road dip on Greenvale at the west end of the bridge where the Progressive Rail tracks cross Greenvale

south to north. The storm water and snow melt drainage in this dip at the Progressive tracks is non-existent or dysfunctional. In the winter, there is always a collection of water, ice, and potholes at this location in Greenvale Avenue. It is my hope that your sidewalk improvements at this railroad crossing will include fixing the storm water drainage.

- 8. The City is apparently proposing to increase the road width or paint-in a bikeway along the north side of St. Olaf Avenue over its entire run from Hwy 3 to St. Olaf College. I offer the same comments about this bikeway as written in Item 2, above. Can there be signage at both ends and along this bikeway to explain where the City wants auto users to drive in the revised street profile after the bikeway is installed? This signage will be particularly important if the revised street profile has no center line for the two-way, auto lanes.
- Your Questionnaire offers an opportunity for homeowners to think about the discharge lines for their sump pumps. It is my hope that this Questionnaire is a sign that the City is beginning to address the management of water from residential sump pumps.

The Association's Board has devoted many hours to managing sump pump water because the City apparently has no requirement for home builders to provide for sump pump discharges when building new homes. Your 2022 Project will not directly impact our neighborhood's water flows; but I endorse any City effort to get management of sump water discharges into the building code and street design projects. This management effort is of growing importance as the City promotes homebuilding on ever smaller lots.

I appreciate this opportunity to comment on the proposed, 2022 NW Area Mill and Overlay Project.

Regards,

Homeowner

Enc: Completed Project Questionnaire



ROADWAY PAVEMENT CONDITION

PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

The City values input from residents who live along the project corridor as you have first-hand knowledge of how the streets and utilities function. Your comments / concerns will assist us during the preliminary design and layout of the project. We encourage you to take a few minutes to fill out the following questionnaire. Completed questionnaires can be collected at the Neighborhood Meeting, emailed to Sean.Simonson@ci.northfield.mn.us or dropped off at the Engineering Office located at Northfield City Hall, 801 Washington Street.

Do you feel the pavement surface has deteriorated to the point it needs to be fixed? Please circle one: YES NO	
2. STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION	
I have observed street ponding after a significant rain. It is located at:	
Some ponding AT LOW PT. OF NORTH AUL	
I have observed areas of erosion along the boulevard at:	
Does your home or business have a sump pump? (address). Yes orXNo If yes, would you be interested in a sump line extended beyond the curb to hook your sump pump discharge toYes orXNo Non-answer - no sump	?
3. SANITARY SEWER	
We have not experienced any problems with our sanitary sewer serviceWe have experienced problems with our sanitary sewer service (address).
4. WATERMAIN	
We have not experienced any problems with our water serviceWe have experienced problems with our water service (address).	

	WALKS ANI							
here side	walks or trail	s that you b	elieve are mis	ssing that need t	o be added to I	he project		
_Yes or	X No							
es, please p	provide loca	tion						
			J WAS	SIDEWA	LV on	Smatus	INT OF	North
Ave 1	ALL R	RADY.	4 442	SIDEWA	CK ON	300143	ing or	TADICTIA
20.04		•	_					
No	Neen 1	on T	RALL C	or Wal	1C, 12 -	this Ar	LLA.	
	RAL COMM			e to he consider	ad as a part of	hasa imarayam	onts:	
				e to be considere	ed as a part of t	these improveme	ents:	
				e to be considere	ed as a part of t	hese improveme	ents:	
				e to be considere	ed as a part of t	hese improveme	ents:	
				e to be considere	ed as a part of t	hese improveme	ents:	
				e to be considere	ed as a part of t	hese improveme	ents:	
				e to be considere	ed as a part of t	these improveme	ents:	
				e to be considere	ed as a part of t	these improveme	ents:	
				e to be considere	ed as a part of t	these improveme	ents:	
				e to be considere	ed as a part of t	these improveme	ents:	
				e to be considere	ed as a part of t	these improveme	ents:	
				e to be considere	ed as a part of t	hese improveme	ents:	
				e to be considere	ed as a part of t	hese improveme	ents:	
				e to be considere	ed as a part of t	these improvement	ents:	
				e to be considere	ed as a part of t	these improvement	ents:	



PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

The City values input from residents who live along the project corridor as you have first-hand knowledge of how the streets and utilities function. Your comments / concerns will assist us during the preliminary design and layout of the project. We encourage you to take a few minutes to fill out the following questionnaire. Completed questionnaires can be collected at the Neighborhood Meeting, emailed to Sean.Simonson@ci.northfield.mn.us or dropped off at the Engineering Office located at Northfield City Hall, 801 Washington Street.

1.	ROADWAY PAVEMENT CONDITION a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed? Please circle one: NO Possessible V	No	THAS
2.	STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION		
-	I have observed street ponding after a significant rain. It is located at:		
_	have observed areas of erosion along the boulevard at:		
Doe	es your home or business have a sump pump? (address		
_	_Yes orNo		
If ye	es, would you be interested in a sump line extended beyond the curb to hook your sump pump discharge to?		8
_	_Yes orNo		The same of the sa
3.	SANITARY SEWER		Ex
V	We have not experienced any problems with our sanitary sewer service. We have experienced problems with our sanitary sewer service (address		ANDI
4.	WATERMAIN		W. I
V	We have not experienced any problems with our water service. We have experienced problems with our water service (address		CNA NE IN
			Re Co
			th 3
			M+

Yes or No
If Yes, please provide location
SOME OF THE STDEWALKS ON OUR
STREET + IN OUR AREA ARE HATARDS
+ NEED TO BE REPAILED
6. GENERAL COMMENTS / QUESTIONS
Please offer any additional information you would like to be considered as a part of these improvements:
PLEASE CONSIDER BETTERNIEBHTING
Apacitic Table Autority (-01)
ALBOND TOTAL THE COLUMN CIGHT
POSTS AROUND TOWN (ESPECIALLY IN
POSTS AROUND TOWN (ESPECIALLY IN POSTS AROUND TOWN (ESPECIALLY IN
RESIDENTIAL AREAS) ARE HERY DIM
THIS IS A SAFETY CONCERN FOR DIME

5.

SIDEWALKS AND TRAILS (WALKING AND BIKING)



PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

The City values input from residents who live along the project corridor as you have first-hand knowledge of how the streets and utilities function. Your comments / concerns will assist us during the preliminary design and layout of the project. We encourage you to take a few minutes to fill out the following questionnaire. Completed questionnaires can be collected at the Neighborhood Meeting, emailed to Sean.Simonson@ci.northfield.mn.us or dropped off at the Engineering Office Jocated at Northfield City Hall, 801 Washington Street.

a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed? (NO) YES Please circle one: STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION 2. I have observed street ponding after a significant rain. It is located at: I have observed areas of erosion along the boulevard at: Does your home or business have a sump pump? (address __Yes or X_No If yes, would you be interested in a sump line extended beyond the curb to hook your sump pump discharge to? Yes or X No Non-answer - no sump SANITARY SEWER 3. We have not experienced any problems with our sanitary sewer service. We have experienced problems with our sanitary sewer service (address ____ WATERMAIN We have not experienced any problems with our water service. We have experienced problems with our water service (address _____

	ewalks or trails that you believe are missing that need to be added to the project
	No e provide location
picas	e provide location
i. GEN	IERAL COMMENTS / QUESTIONS
	1
lease offer	son additional information you would like to be considered as a part of these improvements:
Please offer	Story additional information you would like to be considered as a part of these improvements: Story additional information you would like to be considered as a part of these improvements: Story additional information you would like to be considered as a part of these improvements: Story additional information you would like to be considered as a part of these improvements: Story additional information you would like to be considered as a part of these improvements: Story additional information you would like to be considered as a part of these improvements: Story additional information you would like to be considered as a part of these improvements: Story additional information you would like to be considered as a part of these improvements:
Please offer	son additional information you would like to be considered as a part of these improvements:
Please offer	Street seems to be in very good condition. Now- Surfrised to see it on the transfer down now- Surfrised to see it of the transfer down now- Surfright now- Surfrig
Please offer	Street seems to be in very good condition. Now- Surfised to see it on the Vistostall. Street seems to be in very good condition, now- Surfised to see it on the Vistostall. St. Clat construction may or may not course domage - most bumps" in street are many lote covers. Olat tree west of pincolo intersection is being partially.
Please offer	Street seems to be in very good condition. Now- Surfrised to see it on the transfer down now- Surfrised to see it of the transfer down now- Surfright now- Surfrig
Please offer	Street seems to be in very good condition. Now- Surfrised to see it on the transfer down now- Surfrised to see it of the transfer down now- Surfright now- Surfrig
Please offer	Stolat Avenue Street seems to be in very good condition, now Survivised to see it in the Distarce of the seimprovements: Street seems to be in very good condition, now Survivised to see it in the Distarce of the semantic of the semant
Please offer	Street seems to be in very good condition now- Surfficient to no it in the tist of all Street seems to be in very good condition now- Surfficient to no it in the tist of all Out of construction may or may not course domage - most bumps "in street are (many dole covers) Olat tive west of pincolo interaction is being partially repult by st Olat as part of "Ole five" project - ressuming that is private part of project.
Please offer	Street seems to be in very good condition, now- Street seems to be in very good condition, now- Street seems to be in very good condition, now- Street seems to be in very good condition, now- Street seems to be in very good condition, now- Street seems to be in very good condition, now- Street seems to may or may not course domage - most bumps" in street are many not course domage - most bumps" in street are many not course domage - most conditional information you would like to be any not one of the seems to be many partially reported by St. Clarks you of "Ole Ave "project" - ressuming that is private part of project. TOURS THE ST. NO DUMP OUTS at Stop Signs of corners free a ite 4 show. And pixes will hit
lease offer	Street seems to be in very good condition now- Surfficient to now the Wiston all Condition now- Surfficient to now the Wiston all Condition now- Surfficient to now the Wiston all Conditions now- Street seems to be in very good condition now- Surfficient to now the Wiston all Conditions now- Surfficient to now the Wiston all Conditions now the Condition in Surfficient to hem partially result by St. Out as part of project. The Simps of Marca already for now common or project.



PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

The City values input from residents who live along the project corridor as you have first-hand knowledge of how the streets and utilities function. Your comments / concerns will assist us during the preliminary design and layout of the project. We encourage you to take a few minutes to fill out the following questionnaire. Completed questionnaires can be collected at the Neighborhood Meeting, emailed to Sean.Simonson@ci.northfield.mn.us or dropped off at the Engineering Office located at Northfield City Hall, 801 Washington Street.

 ROADWAY PAVEMENT CONDITION a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed? 	
Please circle one: YES (NO)	
2. STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION	
I have observed street ponding after a significant rain. It is located at:	
The sidewalk between 718 Saint Olat of 720 \$ Saint Olat ponds hadly after leavy re	11
I have observed areas of erosion along the boulevard at:	
Does your home or business have a sump pump? (address).	
Yes orNo	
If yes, would you be interested in a sump line extended beyond the curb to hook your sump pump discharge to?	
Yes orNo	
3. SANITARY SEWER	
We have not experienced any problems with our sanitary sewer serviceWe have experienced problems with our sanitary sewer service (address).	
4. WATERMAIN	
We have not experienced any problems with our water service.	

5.	SIDEWALKS AND TRAILS (WALKING AND BIKING)
Are the	ere sidewalks or trails that you believe are missing that need to be added to the project
Ye	es or No
If Yes,	please provide location
The Transaction	
	GENERAL COMMENTS/QUESTIONS offer any additional information you would like to be considered as a part of these improvements: Int old fire is too narrow to have 18 wheelers going up a drawn it deally, the mussire trucks would get to Stold College by taking 19 to himon. Phase consider disallowing huge trucks on Saint old Att. It street (as they'd don't on the East side by (aviction). It's confusion of our uses it as intended.

From: To:

Sean Simonson

Subject: Date: 2022 NW Area Mill and Overlay Feedback Monday, July 19, 2021 11:40:23 AM

CAUTION: This email originated from outside of the organization.

Dear Sean,

I was unable to attend the community meeting and the 2022 NW Area Mill and Overlay project but I appreciate that the materials have been <u>posted online</u>.

First off, I want to express my support for the sidewalk addition at Highland Ave and Ivanhoe Dr (letter B). My children walk that route to Greenvale Park School and the addition of a sidewalk there will make the route much safer. I prefer Option 1 because it has the fewest number of street crossings.

Second, as a resident of St. Olaf Avenue (letter G), I want to express support for the Shared Lanes (Sharrow) option. Eliminating parking on our street would cause great difficulty for residents (like us) who have a single lane driveway, and the many residents who have shared driveways. Visitors to Way Park would be forced to park on 2nd Street which is a fair distance from the playground and might cause families with young children to avoid coming to the park due to parking difficulties. Events at Way Park (Books & Stars, Vintage Band Festival, Pumpkin Fest) would cause overflow traffic onto the smaller side streets causing congestion in those neighborhoods.

Will there be other opportunities to express our concerns? When will we know which of these options have been chosen?



From:
To: Sean Simonsor


Subject: 2022 NW Area Mill and Overlay
Date: Monday, July 19, 2021 1:01:58 PM

CAUTION: This email originated from outside of the organization.

Dear Sean,

I wrote a few days ago I'm response to the questionnaire sent to residents in this area, and now I'd like to weigh in on the bike lane concepts.

I'm afraid we really do need parking on one side of the street. I live across the street from Way Park, and the parking lane is often full, whether for skaters in the winter, families at the playground, or groups gathering for picnics. Even one side doesn't suffice at certain times like during events in Way Park or when construction vehicles are lining the street. So I'd favor the option that leaves a parking lane and shared lanes for cars and bikes.



From:
To: Sean Simonson

Subject: 2022 NW Area Mill and Overlay--St. Olaf Ave.

Date: Sunday, July 18, 2021 11:01:44 AM

CAUTION: This email originated from outside of the organization.

Dear Sean,

I appreciate the clear information provided for next summer's street project, and, since I could not attend the July 14 information session, am glad that the meeting materials are available on the city website. If you are keeping an email list of those to be notified of future developments, please add me to that list.

As far as drainage and paving problems are concerned, here in the 700 block the pavement is still fairly decent, but we also have quite a few construction trucks going back and forth for various projects, so it is heavily trafficked in two senses of the word. Around the RR tracks, there are definitely rough spots, and the St. Oaf Ave/Orchard intersection is rough as well.

I have not noted water pooling, and have had no problems in that area, except for a sudden and unexplained wet basement two summers ago. It seemed to be seeping in from the south—street—side and was the first time we'd had water in the basement in the 50 years we've lived here. At that point I had a sump pump installed, but frankly have not noted that it has been running. Anyway, the basement is dry. My next door neighbors reported water in their basement at the same time, but I don't know if that has persisted.

Thank you,



From:
To: Sean Simonso
Cc:

Subject: Comments on 2022 NW Mill and Overlay Project

Date: Monday, July 12, 2021 5:05:39 PM

CAUTION: This email originated from outside of the organization

Dear Mr. Simonson,

We would like to comm	nent on the proposed stree	t overlay and bike lane addition to St. Olaf
Avenue next summer.	We have lived at	for 28 years, directly across
the street from the	. Please accept this e	email message in lieu of the provided form a
it was not able to be fill	ed out online.	

Our questions and/or concerns are:

- This project is scheduled for next summer, but the St. Olaf construction is not scheduled to be done until the end of summer. How can these two projects be accomplished at the same time?
- Does the addition of bike lanes require the elimination of parking on the south side of St. Olaf Avenue for the Ole Store, Way Park and residents? Currently there is no parking on the north side of the street. Eliminating on-street parking is a big loss to residents, visitors and Ole Store patrons.
- St. Olaf Avenue is already a narrow street for the amount of traffic it carries. Are the addition of bike lanes even possible without widening the street?
- Is St. Olaf Avenue the best street to direct bikes to because of the amount of traffic on
 the street and that it connects the College to a busy highway without a safe place
 to cross? This plan would dump bicycle traffic onto HWY 3,
 necessitating changing of lanes and making a left turn across traffic to get downtown
 or back. This seems unnecessarily dangerous for bike riders, many of them children.
- Would a better choice for bike lanes be Second Street or Forest Avenue which carry less traffic, use almost no commercial on-street parking, and delivers cyclists to controlled crossing areas of HWY3?

and are in favor of street improvements with the overlay and creating safe bike routes. However, we ask that it be delayed until the St. Olaf construction project is done, lest it create a chaotic circumstance of finishing the buildings and moving students in while the street is torn up, or worse, damaging newly overlayed streets. Further, I recall that St. Olaf suggested during City Council and Planning Commission meetings for the building project that they would pay for street damage caused by construction vehicles. I would ask that this be confirmed, particularly if this is all happening simultaneously.

We STRONGLY request that bike lanes be placed on streets that can utilize safe crossings of HWY3 and are wide enough to handle the simultaneous tasks of driving cars, parking and riding bikes. We do not believe St. Olaf Avenue is the best option available.

Our thanks,

 From:
 Sean Simonson

 Cc:
 Rhonda Pownell

Subject: Neighborhood Meeting Questionnaire Reponses

Date: Tuesday, July 13, 2021 8:02:47 PM

CAUTION: This email originated from outside of the organization.

Sean and Mayor Pownell,

I'm writing regarding the 2022 project letter we received as neighbors and residents that will be affected by this project. Thank you for soliciting feedback - that is very much appreciated.

- the corner of
. We have the drainage pond in our backyard, as well as the large City
drain on the corner of our property. When we first learned about this project, we made an
assumption (bad on our part) that the project here would be similar to what was just completed
on the east side of John North Park, paint on the street, so that this corridor of the city had
continuity in the appearance, and at least to us, that seemed to make sense. It was surprising to
us, to learn instead, that a trail was going to be constructed on the north side of North Ave.

We moved here 10 years ago because it was a special place in Northfield. A quiet gem that was still left intact with mature trees and homes with larger plots of land. Wang's Woods, we were told, is a wetland area that would never be built on - clearly we didn't do all of our homework; we know the property lines and we know the easement rights, we naively never thought the city would seek to put a trail through a wetland property. In our yard last year we had owls, cardinals, blue jays and woodchucks; 2 hawks made their home here, baby deer hang out with their parents at the pond, the mallard ducks have returned every year we've lived here to hatch their ducklings (much to the happiness of the hawk!). My point is, in addition to this project affecting our property, it also affects the wildlife that call this area home. They will leave when their water source is no more, and when it is no longer safe for them to raise their young here.

I also question the need. What were the driving factors to put a trail on the north side of North? Selfishly, I look up and down North and see many homes that will be impacted by the removal of the big beautiful trees and greenery that provide shade and privacy for all of us, our home included. I want all to have access to safe roads and trails to ride and roll and be able to be out and about. There is a sidewalk on the south side of North - has widening that been considered in addition to painting the street for the bikes? Putting a trail on the southsdie would ensure that the senior living community could use it safely (1000 Cannon and NRC) without having to hurry across North to connect. That would seemingly be way more cost effective as well. What about bump outs to slow down traffic and make safe crossings? Paint the crosswalks for safe crossings? At the beginning of the pandemic, when the only thing we could all do safely was be out of our houses and exploring nature, there was never an issue of being too close to other people, of folks not having space to bike or roll. How was the need for this project assessed? It appears that in past studies, a project on North was not in consideration.

While I'm not super excited about a trail running next to our once quiet property, I'm far more concerned about the drainage in this area. When it rains, our sump pump runs constantly. We sit at the bottom of the hill and that little pond has gone up and over it's banks almost every year that we've lived here; I can't imagine what sort of water issues we and our neighbors will

have when there is pavement in place of the soil in our yard. What sort of mitigation efforts will be in place to ensure that the water issues won't get worse? Is the drain being relocated? That seems like a pretty expensive project! I'm also not excited about the potential drop in our property value; again, the charm and the value of this home lies in the peace of the woods.

My husband and I look forward to attending the Neighborhood meeting tomorrow night to learn more. Again, I appreciate that you sought the feedback from those of us that call this area home. We look forward to seeing you tomorrow.



"It is never too late to be what you might have been." ~George Eliot

From:
To: Sean Simonso

Subject: project questionnaire for 2022 NW Area Mill and Overlay Project

Date: Monday, July 19, 2021 5:16:23 PM

CAUTION: This email originated from outside of the organization.

Hi Sean,

First, let me say how appalled I was at the audience questions at the public meeting last week. Most were inappropriate and rude. Instead of coming together to provide constructive feedback, it turned out to be a small number of vocal individuals attacking you and your team. You showed a tremendous amount of patience.

My only feedback for you is how to establish a bike lane along North Ave. I like the idea of a connected bike trail system, and, in the case of North Ave., it sure seems a better fit and more cost effective to build this on the existing road like what the City did on Lockwood Drive last year. The amount of disruption installing a new bike trail on the right-of-way on the north side of North Ave. would be significant, including the removal of so many nice shade trees and relocation of utilities.

Good luck in your planning,



Sean Simonson North Ave Project

Date: Saturday, July 17, 2021 11:18:20 AM

CAUTION: This email originated from outside of the organization.

Dear Sean,

I had previously completed the questionnaire to express opposition to sidewalks in the Woodland Trail area. Given that the proposal now includes an off-street trail on North Ave, I wish to express my strong opposition to that. The basis of my opposition is the taxpayer expense, the destruction of trees, and the minimal benefit.

Thank you,



From:

To: Sean Simonson; Rhonda Pownell
Subject: NW Northwest Mill Meeting of 07/14/21
Date: Thursday, July 15, 2021 8:49:26 AM

CAUTION: This email originated from outside of the organization.

Sean:

We attended the meeting last evening pertaining to the above street project. We thought it was well attended.

A couple of items stuck out:

- 1. Nobody wants the trail on the north side of North Avenue
- 2. Whether there's a 2:1 tree replacement set up or not, people are worried about the great loss of trees.
- 3. Looking at the last slide of your program and the description of the the "On-Street Bikeway/Trail" for North Avenue, is clearly something that needs to be discussed. The clear choice, when discussed with property owners on North Avenue, is the On-Street Bikeway has virtually NO resistance!!!! You'll have plenty of support if that option is chosen rather than the Trail.

Thank you for the informative meeting.



POADWAY PAVEMENT CONDITION

PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

The City values input from residents who live along the project corridor as you have first-hand knowledge of how the streets and utilities function. Your comments / concerns will assist us during the preliminary design and layout of the project. We encourage you to take a few minutes to fill out the following questionnaire. Completed questionnaires can be collected at the Neighborhood Meeting, emailed to Sean.Simonson@ci.northfield.mn.us or dropped off at the Engineering Office located at Northfield City Hall, 801 Washington Street.

1.	a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed? Please circle one: NO
2.	STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION
X	I have observed street ponding after a significant rain. It is located at:
Non	holde of Northshe: west of Dubthshe, by North Booster Station
_	I have observed areas of erosion along the boulevard at:
Does	your home or business have a sump pump? (address).
X	/es orNo
If yes,	would you be interested in a sump line extended beyond the curb to hook your sump pump discharge to?
	les or No N/A- done in 2019
3.	SANITARY SEWER
X	_We have not experienced any problems with our sanitary sewer serviceWe have experienced problems with our sanitary sewer service (address).
4,	WATERMAIN
X	_We have not experienced any problems with our water serviceWe have experienced problems with our water service (address).

5. SIDEWALKS AND TRAILS (WALKING AND BIKING)	
Are there sidewalks or trails that you believe are missing that need to be added to the project	
Yes or $^{1}\!$	
1es or No	
If Yes, please provide location	
	-
6. GENERAL COMMENTS / QUESTIONS Please offer any additional information you would like to be considered as a part of these improvements:	
Please offer any additional information you would like to be considered as a part of these improvements:	
Please offer any additional information you would like to be considered as a part of these improvements:	
Please offer any additional information you would like to be considered as a part of these improvements:	
Please offer any additional information you would like to be considered as a part of these improvements:	
Please offer any additional information you would like to be considered as a part of these improvements:	
Please offer any additional information you would like to be considered as a part of these improvements:	
Please offer any additional information you would like to be considered as a part of these improvements:	
Please offer any additional information you would like to be considered as a part of these improvements:	
Please offer any additional information you would like to be considered as a part of these improvements:	
Please offer any additional information you would like to be considered as a part of these improvements:	
Please offer any additional information you would like to be considered as a part of these improvements:	
Please offer any additional information you would like to be considered as a part of these improvements:	
Please offer any additional information you would like to be considered as a part of these improvements:	
Please offer any additional information you would like to be considered as a part of these improvements:	
Please offer any additional information you would like to be considered as a part of these improvements:	
Please offer any additional information you would like to be considered as a part of these improvements:	
Please offer any additional information you would like to be considered as a part of these improvements:	
Please offer any additional information you would like to be considered as a part of these improvements:	

From: To:

Sean Simonson

Subject:

Proposed North Ave Trail

Date: Friday, July 09, 2021 1:49:45 PM

CAUTION: This email originated from outside of the organization.

Mr. Simonson,

There is a proposed trail to be built along the north side of North Ave running from Eveleth Ave to Zanmiller Dr included on the recent map we received of 2022 Construction Projects. This trail will result in the removal of NUMEROUS trees. Many property owners have beautiful landscaping that would need to be destroyed. The traffic on North Ave is never very busy so bike riders are safe on the street. There is a sidewalk along the south side of North Ave for pedestrians. The money spent on this trail could be used on a project that would benefit a lot more people than the few that would use this trail. Please do not build this trail. It is a waste of time and money.

Sincerely,

From:
To:
Sean Simonson

Subject: 2022 Proposed Mill and Overlay Project Date: Friday, July 16, 2021 6:30:03 AM

CAUTION: This email originated from outside of the organization.

As a resident of , I would like to endorse the following:

- 1). On street buffered bike lane for North Avenue between Cedar/Eveleth and North Park.
- 2) Minimal tree trimming/removal along Woodland Trail.

Sincerely,

From:

To: Sean Simonson

Subject: 2022 Proposed Improvements...Bike Trail

Date: Friday, July 16, 2021 11:02:53 AM

CAUTION: This email originated from outside of the organization.

We live at _____, street and sewer improvements completed in 2019. Our comments about the proposed bike trail addition to be included with North Avenue improvements follow.

We are retirees with young grandchildren who visit weekly. We bike frequently with and without grandkids. Any safety improvement to biking on North Avenue would be welcome. Currently we only permit the grandkids on the sidewalk along North Ave (city ordinance violation?).

The presentation material on July 14 included 3 options for North Avenue. We are in favor of the cycle lane option. It saves trees and provides a barrier between bikers and traffic. The buffer option is merely a bike stripe. If it were a true buffer with posts along the route, we would have selected that.

Eliminating parking on North Ave will have minimal impact at Summerfield Apts. Spring/summer usually have 4 cars parked on North Ave. Fall/winter it increases to 5 or 6. There are always parking spaces available in the lot provided. While we have not researched this, we believe parking on North Ave is a matter of convenience not a lack of parking availability in the lot.

Thanks for the opportunity to comment.



From:
To: Sean Simonson
Cc:

Subject: Proposed 2022 NW Area Project, specifically a new trail along North Avenue

Date: Monday, July 12, 2021 3:02:54 PM

CAUTION: This email originated from outside of the organization.

Hello Sean,
My name is _____, and I wanted to detail in writing my significant concerns with this project before the meeting on Wednesday, specifically the development of a trail along North Avenue. To summarize, my questions can be condensed as follows:

- 1) Why is this being considered? Who wants this trail? Why is this being built? What problems will it solve? There is already a sidewalk along the entire south side of North Avenue. A new trail seems completely redundant.
- 2) Along those same lines, where is the traffic study? Who will use this trail, and how much will they use it, especially considering there is a sidewalk along the other side of the road?
- 3) What other alternatives have been studied? Why is a separate paved path considered the best option?
- 4) The houses in Wang's Woods (the common name for the Woodland Trail neighborhood north of North Avenue) were built on a wetland. We all have sump pumps and there are drainage issues (standing water in multiple areas) after significant rain events. How will the problems that will come from putting in more impervious surface be addressed? Also, how will the affected homeowners be compensated for the lost of significant land, as well as mature, beautiful trees? (I would argue the trees add more long-term value to North Avenue than a paved trail would.)

My husband and I have lived at for the past 22 years. I am a runner, and use the trails through Prairie Hills Park and North Park on a daily basis. I walk my dog along the sidewalks in my immediate neighborhood three times a day. Our kids, who are now 20 and 16, walked or biked to Greenvale Park Elementary daily. I feel like I have a pretty good handle on the trail and sidewalk conditions year-round, as well as the pedestrian and bike needs in the northwest area of town. Along with my neighbors, we have thought of many other less costly (both in terms of money and climate) alternatives that should be considered before charging ahead with a separate paved trail:

- 1) Paint the crosswalks and put up "Pedestrian Crossing" signs, especially across North Avenue at Cannon Valley Drive, at Ensley and North, and at Summerfield and North. (The painting is a minimum, and should be done regardless. Honestly, all of the crosswalks in the Dakota County/NW section of Northfield need repainting on a regular basis, no matter if they're scheduled for mill & overlay or not.) If memory serves, the crosswalks have been painted only ONCE in our 22 years here. (I am probably wrong on this, but they have certainly not been repainted in the last 5 years.) I was just near Second Street and Oak last week, taking my dog for a run in the Upper Arb, and the amount of paint on the roads (for crosswalks and bike lanes) in the northeast part of town is almost overwhelming in comparison.
- 2) Enforce the snow shoveling ordinances for homeowners, and make sure the city plows the trails in Prairie Hills Park and North Park. Some homeowners are great, but others certainly do not follow the law. This forces me and my dog to walk along the street so as not to slip and fall on the accumulating ice.
- 3) Mow the right of way between both ends of Woodland Trail and North Avenue, and take down buckthorn and other small bushes at those corners which obscure the sight lines. Because we had a new driver in our house last summer, I went out with the loppers myself so that he could look east along North Avenue to see oncoming traffic before turning right.
- 4) If a trail is still considered to be necessary, please consider banning parking on BOTH sides of North Avenue (currently only the north side is banned), institute a 25-mile-per-hour speed limit, and paint an onstreet bikeway. Along those lines, enforce the speed limit along North Avenue, period.

I have talked to multiple neighbors, all of whom walk, bike, and spend time on the sidewalks and trails, and we all feel sideswiped by this. Of those I have talked to, no one is in favor of this, and cannot understand the need for or the reasoning behind this decision. If it is just to say "we have added another mile of bike trail in Northfield!" that is not a good enough reason. If it is just because the Toole Design engineers put it in the March 2019 "City of Northfield Pedestrian Bike and Trail System" final report as an option (when it didn't list the North Avenue corridor as a problem or "gap" area for either biking or

pedestrian needs), that is not a good enough reason. If it is to promote a safer route to school (I lived it! I am in favor of it!), kids would still have to cross North Avenue to get to Greenvale and that is not as safe as it could be -- a trail would only exacerbate the existing issues. I am all for promoting pedestrian and bicycle routes in our wonderful town -- but let's please spend the money wisely, where there is an actual need voiced by the neighborhood.

I hope to talk to you in person at the meeting on Wednesday.

From:
To: Sean Simonson

Subject: Northfield on-street bikeway improvements and trails

Date: Wednesday, July 14, 2021 11:07:06 AM

CAUTION: This email originated from outside of the organization.

I have concerns about the bikeway paths being developed in town, particularly those on Lockwood Drive and probably Thye Parkway. I have loved biking all my life and biked all around town and on trails for about 45 years. BUT, making bike trails out of city streets doesn't make sense to me. I agree with bike lanes on the side of the street, but making the entire street a bike trail is too much. In order to get to downtown or anywhere else from our residence, we will have to drive bike trails--driving at bike speeds when there are bikes there. I would like a street to drive on. Right now, the city has invested in many signs and much painting on the street, indicating bikes have the right of way on the street---essentially making it a bike trail, not a street for car traffic. I hope you will reassess this plan.



ROADWAY PAVEMENT CONDITION

1.

PROJECT QUESTIONNAIRE

2022 NW Area Mill and Overlay Project Northfield, Minnesota

The City values input from residents who live along the project corridor as you have first-hand knowledge of how the streets and utilities function. Your comments / concerns will assist us during the preliminary design and layout of the project. We encourage you to take a few minutes to fill out the following questionnaire. Completed questionnaires can be collected at the Neighborhood Meeting, emailed to Sean.Simonson@ci.northfield.mn.us or dropped off at the Engineering Office located at Northfield City Hall, 801 Washington Street.

a. Do you feel the pavement surface has deteriorated to the point it needs to be fixed? Please circle one: NO
2. STORM SEWER, STORM WATER DRAINAGE AND SURFACE EROSION
I have observed street ponding after a significant rain. It is located at:
1765 Quie Lane, Northfield - several places where the water does not flow the drain, creates ice groblems in winter I have observed areas of erosion along the boulevard at:
Does your home or business have a sump pump? (address).
Yes or X No - No Basement
If yes, would you be interested in a sump line extended beyond the curb to hook your sump pump discharge to?
X yes or I No - For Neighborat
3. SANITARY SEWER
4. WATERMAIN
We have not experienced any problems with our water service. We have experienced problems with our water service (address



From: To:

Sean Simonson

Subject: Date: Project Questionnaire -- NW Area Monday, July 12, 2021 2:23:30 PM

CAUTION: This email originated from outside of the organization.

Sean,

I am not able to attend this week's meeting due to prior commitments. Attached is my response to survey sent in mail.

If you have any questions about my responses, please call /email me contact info below.

Resurfacing of Lockwood, Thye -- Agree - work needs to be done.

On Street Bikeway -- NOT necessary -- to redo the roads and then mess them up with bike paintings and more signs seems a waste of money - -- the duplicate painting of "bikes" on south end of Lockwood made a mess of a perfectly new road! Cyclists have always used the road and will continue to do so with or with OUT the painting/marking.

Trail - NOT necessary!!! there is already a trail that meets Thye on the East side of the Liberty Park Land.

Instead -- USE THE FUNDS to create a neighborhood park that includes a 1) PUBLIC tennis/pickleball court (there are no general tennis courts for our citizens to use - when school is in session MS and HS teams use the school courts AND they are all on the south side of town!) 2) Outdoor Rink wit boards during winter months 3) Sand Volleyball

Active community member,





Comments on the Ivanhoe Dr. Sidewalk

This sidewalk project must be a top priority for no later than 2020. Completion before the next school year would be even better. This segment of pedestrian walkway has been identified as a "need" on the "Safe Routes to School" studies for years. A designated walking route should not require 5- and 6-year-old children to walk for a block in a city street, especially when there is a dangerous corner at each end of that block. Over the past school year, we have observed many children, including a group of six to ten pedestrians including small children and parents, regularly walking home in the street on this block.

The sidewalk route shown in the Engineering drawing is highly preferable because it allows pedestrians (especially small children) to cross only one street to get from the end of the sidewalk on Manitou St to the entrance of the city provided path. That street is Highland Ave. that is a block long dead end so hopefully there is minimal traffic, (unless Reese and Schmidt covert it to an access to the Kraewood development.)

That said, there are two major design challenges for the design engineers. The most critical issue is that a sidewalk as shown will not necessarily be used as expected. Pedestrians, whether 6 or 86 years old, will be tempted to take the shortest, straight-line route from Manitou to the path. The sidewalk will require creative features at both ends to discourage pedestrians from walking into the street at both ends. These features will have to include barriers and/or landscaping that directs to walkers to use the sidewalk.

The second issue deals with interface between the sidewalk and the properties along the route. The city has the right-away available. If the city had installed the sidewalk 50 years ago when the school was first built there would be no issue. However, 50 years later the homeowners along the route have installed landscaping. It is imperative that the city work with these individuals and the citizens as a group to minimize the impact on the existing lawns.

Please do not kick the can down the road again, make this sidewalk happen.

