

## Certificate of Appropriateness for 312-314 Division St S. (McKay & Tosney Buildings) Façade Changes

HERITAGE PRESERVATION COMMISSION

APRIL 14, 2022

REVEE NEEDHAM, ASSISTANT CITY PLANNER



Current
Conditions of
312 Division St S.
(McKay Building)
& 314 Division
St. S (Tosney
Building)





- 1. Remove and replace some wood panels on the front façade
- 2. Repair and repaint masonry
- 3. Replace the storefront windows
- 4. Replace the upper story windows
- 5. Replace the awnings





Overall Design

Community Development
Department



•The wood panels will be removed to reveal masonry, which will be repaired

•Some wood panels covering cinder blocks will be replaced




1. Remove & Replace Wood Panels



Northfield Yarn



•Applicant will repair and tuckpoint masonry as needed, following best practices for building maintenance







2. Repair and Repaint Masonry

Current Conditions: Masonry is in need of repair



•Colors are sufficiently contrasting and comprised of earth tones, and mainly come from the Sherwin Williams historic collection

Storefront of both buildings; cornice of Tosney building

SW 2819

Downing Slate
Interior / Exterior

SW 27562

SW 7562

Primary color for Tosney Building; window frame & cornice of McKay building

Accent color for the doors of both buildings; window frames of Tosney Building

Interior / Exterior Location Number: 148-C5 Roman Column Interior Location Number: 263-C1

Primary color for McKay building

Colors



•Current Storefront windows are in need of repair



## 3. Replace Storefront Windows






Community Development Department



- •Multi-panes are not original, applicant proposes single-pane storefront window custom-built to fit the existing opening with bronze-colored frame
- Traditional storefront design will be retained and enhanced






3. Replace Storefront Windows




- •It is unknown if multi-pane windows are original, which would be unusual for the simple upper story facade. Applicant proposes single pane double hung windows (A)
- Applicant proposes removing AC at a future time enhancing the look from the street



Close up of existing window



A) Single-pane option – Applicant Preferred



B) Multi-pane option


4. Replace
Upper Story
Windows –
McKay Building




 Applicant proposes single pane double hung windows to fit in the existing openings



Close up of existing window





Community Development Department





•New awning will be retractable canvas that matches the storefront colors, and will be free of graphics or signs



5. Replace Awnings





North

Questions?

Applicant and Contractor will be available for questions

Community Development Department