



# Blight and Nuisance Conditions at 504 6<sup>th</sup> Street East

#### Construction materials and junk on front porch




### Porch left side junk and construction materials



# Porch right side junk and construction materials




#### Driveway with furniture, junk and construction materials




## Brush and garbage in driveway




#### Back of driveway - backyard junk and construction materials



## Back of driveway, construction materials and wood



# Backyard – construction materials and equipment



#### Backyard – construction materials and wood

