

APPENDIX B
Archival and Current Exterior Photos

West Wall (Track side)



1896

-used with permission of Carleton College Archives

Visible Features: Limestone foundation, water table, and window sill; steps spanning most of the wall; cottage style windows; large brackets; order board lamp signal; swooping, flared roof; roof cap, cresting and finials; detailed chimney.



2019

South Wall



Before 1910

-used with permission of Northfield Historical Society

Visible Features: Limestone foundation, water table, and window sill; two windows in men's waiting room; swooping roof; roof cap and cresting; detailed chimney.



2019

East wall

No archival photos of east walls (main room and baggage room walls)



Before 1910

-used with permission of Northfield Historical Society

The above photo shows the depot west and north walls. It also shows the platform leading around to the east side baggage room door and the east side entrance to the main waiting room for women (see floor plan in Appendix A). The east wall would have included the platform on both the north end for women and on the south end for men. Photo also shows the outhouse for the depot (between depot and “*Lime, Cement, Lehigh Coal*” shed) used until the baggage room was converted in 1910 to two restrooms and a coal bin and boiler room.



North wall



Before 1910

-used with permission of Northfield Historical Society

Visible Features: Limestone foundation, two windows in women's waiting room, swooping roof, roof cap on baggage room, Northfield sign, order blade signal, chimney (in center for heating stove in center serving both waiting rooms), baggage room door for women (far left).



2019